









Parts List


Tools Included



Alignment of the threaded insert may require a screwdriver.



4



5

