


# MECP10K Pump Rebuild Kit

REBUILD PARTS			
Item	Qty	Description	Order Part Number
1	1	<b>Vernier valve assembly</b>	1010076
2	1	<b>Bleed valve assembly</b>	included
3	1	<b>Pump shaft assembly</b>	included
4	1	<b>Output valve assembly</b>	included
5	1	<b>Input valve assembly</b>	included
6	1	<b>Reservoir assembly</b>	1010047

Notes:

1. Lubricate Items 1, 2 and 3 with Dow 111 lubricant.



**MARTEL ELECTRONICS**

Martel Electronics Corporation

3 Corporate Park Drive, Unit 1

Derry, NH 03038

800-821-0023 • 603-434-1433

Fax 603-434-1653

Email: [sales@martelcorp.com](mailto:sales@martelcorp.com)

Website: [www.martelcalibrators.com](http://www.martelcalibrators.com)

P/N 0210076 Rev. A