


Optional Accessories

Order No.	Type	Description
05CZA662	B	Connecting cable (1 m)
05CZA663	B	Connecting cable (2 m)
06AFM380B	B	USB Input Tool Direct (2 m)
02AZD790B	B	Connecting cables for U-WAVE-T (160 mm)
02AZE140B	B	Connecting cables for U-WAVE-T For foot switch

DIMENSIONS



Standard Accessories

Heat shield (04AAB969A: 293-100-10
04AAB969B: 293-130-10) x1

Lithium battery CR2032 (1 pc.),
for initial operational checks (standard accessory)

Spanner (200877) x1

Screwdriver (**04AAB985**) x1

Cleaning paper for measuring faces 1000 sheets
Inspection certificate



Note: To install the heat shield, use the screws attached to the bottom of the micrometer frame.