

PIECAL 311 Automated Universal RTD Calibrator



205 Westwood Ave Long Branch, NJ 07740 1-877-742-TEST (8378) Fax: (732) 222-7088 salesteam@Tequipment.NET

Easy to use

With the PIECAL 311 you can check & calibrate all your RTD instruments and measure RTD Sensors. Automatic indication of connections on the display for simple hookups.

• Take it into the shop, plant or field

Carry it without worry - it comes protected with a rubber boot and rugged, low profile switch. Easy to operate even in the dark areas of the plant with the backlit display.

• Calibrate directly in temperature (°C & °F)

Stop carrying around a decade box and RTD resistance tables. The PIECAL 311 works with the RTDs you use including Platinum 100 (alpha = 3850, 3902, 3926) & 1000 (alpha = 3850, 3750) Ohm, Copper 10 & 50 Ohm, and Nickel 120 Ohm. Easily set any value quickly to within 0.1° with the adjustable digital potentiometer "**DIAL**" plus store any three temperatures for instant recall with the EZ-CHECK[™] switch. Or use like a decade box from 0.00 to 410.00 and from 0.0 to 4001.0 Ohms.

• Fast calibration with automatic output stepping

Choose between 2, 3, 5, 11 and 21 steps to automatically increment the output in 100%, 50%, 25%, 10% or 5% of span. Select the step time to match your system from 5, 6, 7, 8, 9, 10, 15, 20, 25, 30 and 60 seconds.

• Compatible with ALL process instruments

No competitor's calibrator is compatible with as many process instruments! Connect directly to the RTD inputs of smart transmitters, PLCs, DCS and multichannel recorders and verify their outputs or displays. Works with older instruments with fixed excitation currents and newer multichannel instruments that switch the excitation current between input channels.

<complex-block><complex-block>

Actual Size

• Measure RTD sensors

Trouble shoot sensor connections and find broken wires with patented technology. Connect your two, three or four wire RTDs and the PIECAL 311 automatically detects the connections and measures the RTD in degrees C or F. Secondary display shows the resistance value corresponding to the RTD temperature.

Evolutionary design

PIECAL Calibrators are designed and built by members of the same team that designed and built the calibrators manufactured by Fluke* under the Altek* label. The PIECAL 311 improves upon other brands by including a rubber boot, tilt stand, backlit display with larger digits, rugged switches and a battery compartment for fast battery changes.

* PIECAL Calibrators are not manufactured or distributed by Fluke Corp or Altek Industries Inc, manufacturers of Altek Calibrators. CE

Practical Instrument Electronics 82 E. Main Street Suite 3.14 • Webster, NY 14580 Tel: 585.872.9350 • Fax: 585.872.2638 • sales@piecal.com • www.piecal.com

PIECAL 311 Specifications

General					
Accuracy	±(0.015% of Reading + 0.05 Ohms)				
Temperature Drift	\pm 0.01% of span outside of 23°C \pm 10 °C (73°C \pm 18 °F)				
Operating Temperature Range	-25 to 60 °C (-10 to 140 °F)				
Relative Humidity Range	10 % ≤RH ≤90 % (0 to 35 °C), Non-condensing				
	10 % ≤RH≤ 70 % (35 to 60 °C), Non-condensing				
Size	5.63 x 3.00 x 1.60 in, 143 x 76 x 41 mm (L x W x H)				
Weight	12.1 ounces, 0.34 kg (including boot & batteries)				
Batteries	Four "AA" Alkaline 1.5V (LR6)				
Battery Life	50 Hours				
Optional NiMh Rechargeable battery kit	120 VAC for North America Only; charger, four NiMh batteries, AC & DC cords [Part # 020-0103]				
Low Battery	Low battery indication with nominal I hour of operation left				
Protection against misconnection	Over-voltage protection to 60 V dc (rated for 30 seconds)				
Display	High contrast graphic liquid crystal display. LED backlighting for use in low lit areas.				

Ranges & Accuracie

RTD	Alpha	Degrees C		Degrees F	
Туре	rupria	Range	°C	Range	°F
Pt 100 Ohm	1.3850	-200.0 to -150.0	±0.1°	-328.0 to -238.0	±0.2°
DIN/IEC/JIS 1989	(0.00385)	-150.0 to 360.0	±0.2°	-238.0 to 660.0	±0.4°
Based on ITS-90	()	360.0 to 740.0	±0.3°	660.0 to 1364.0	±0.6°
		740.0 to 850.0	±0.4°	1364.0 to 1562.0	±0.7°
Pt 100 Ohm	1.3902	-195.6 to -100.0	±0.1°	-320.1 to -148.0	±0.3°
(Burns)	(0.003902)	-100.0 to 370.0	±0.2°	-148.0 to 698.0	±0.4°
	· ,	370.0 to 648.9	±0.3°	698.0 to 1200.0	±0.6°
Pt 100 Ohm	1.3916	-200.0 to -140.0	±0.1°	-328.0 to -220.0	±0.2°
(Old JIS 1981)	(0.003916)	-140.0 to 130.0	±0.2°	-220.0 to 266.0	±0.3°
		130.0 to 370.0	±0.2°	266.0 to 698.0	±0.4°
		370.0 to 648.9	±0.3°	698.0 to 1200.0	±0.5°
Pt 100 Ohm	1.3926	-200.0 to -140.0	±0.1°	-328.0 to -220.0	±0.2°
(US Lab)	(0.003926)	-140.0 to 130.0	±0.2°	-220.0 to 266.0	±0.3°
		130.0 to 380.0	±0.2°	266.0 to 716.0	±0.4°
		380.0 to 610.0	±0.3°	716.0 to 1130.0	±0.5°
		610.0 to 850.0	±0.4°	1130.0 to 1562.0	±0.7°
Pt 1000 Ohm	1.3850	-200.0 to 170.0	±0.1°	-328.0 to 338.0	±0.2°
DIN/IEC/JIS 1989	(0.00385)	170.0 to 470.0	±0.2°	338.0 to 878.0	±0.4°
		470.0 to 730.0	±0.2°	878.0 to 1346.0	±0.4°
		730.0 to 850.0	±0.3°	1346.0 to 1562.0	±0.5°
Pt 1000 Ohm	1.3750	-200.0 to 200.0	±0.2°	-328.0 to 392.0	±0.4°
Hy-Cal HVAC	(0.00375)	200.0 to 600.0	±0.3°	392.0 to 1112.0	±0.6°
		600.0 to 850.0	±0.4°	1112.0 to 1562.0	±0.7°
Copper 10 Ohm	1.4274	-200.0 to -150.0	±1.2°	-328.0 to -238.0	±2.2°
(Minco)	(0.004274)	-150.0 to 260.0	±1.4°	-238.0 to 500.0	±2.4°
Copper 50 Ohm	1.4280	-50.0 to 150.0	±0.3°	-58.0 to 302.0	±0.5°
	(0.00428)				
Ni 120 Ohm	1.6720	-80.0 to 260.0	±0.1°	-112.0 to 500.0	±0.2°
(Pure)	(0.00672)				



v lit areas.			Additional Information				
es			PIE Calibrators are manufactured in the USA. This product is calibrated on equipment traceable to NIST and includes a Certificate of				
	Degrees F Range	°F	Calibration. Test Data is available for an additional charge. Practical Instrument Electronics recommends a calibration interva				
	-328.0 to -238.0	±0.2° +0.4°	of one year. Contact your local representative for recalibration and repair services.				

Warranty

0.9 mA to 401 Ohms, 0.4 mA to 4010 Ohms (nominal)

0.025 mV

mA Excitation Current

400 Ohm Range: 10.2 mA max; steady or pulsed/intermittent

4000 Ohms Range: I mA max; steady or pulsed/intermittent

+ 0.05 Ohms)

50/60 Hz, 50 dB

50/60 Hz, 120 dB

±(0.015% of Rdg +-

±(0.015% of Reading + 0.05 Ohms)

DC to 0.01 second pulse width

Add 0.1 Ohms to 3 Wire & 4 Wire Accuracy 0.00 to 401.00, 0.0 to 4010.0 Ohms

Our equipment is warranted against defective material and workmanship (excluding batteries) for a period of three years from the date of shipment. Claims under warranty can be made by returning the equipment prepaid to our factory. The equipment will be repaired, replaced or adjusted at our option. The liability of Practical Instrument Electronics (PIE) is restricted to that given under our warranty. No responsibility is accepted for damage, loss or other expense incurred through sale or use of our equipment. Under no condition shall Practical Instrument Electronics, Inc. be liable for any special, incidental or consequential damage.

Accessories					
Included:					
Red Rubber Boot, Four "AA" Alkaline batteries, Certificate of Calibration					
Deluxe Hands Free Carrying Case	Part No. 020-0211				
Evolution RTD Wire Kit	Part No. 020-0208				
2 Red & 2 Black Leads with Banana Plugs & Spade	Lugs				
Optional:	0				
Ni-MH 1 Hour Charger with 4 Ni-MH AA Batteries	Part No. 020-0103				

(100-120 V AC input for North America Only)

Available From:



An Interworld Highway, LLC Company

(Unless otherwise indicated all specifications are rated from a nominal 23°C, 70% RH for 1 year from calibration)

Read

Source

Excitation Current

3 & 4 Wire Accuracy From I to 10.2 mA

External Excitation Current

Below I mA of External

Excitation Current 2 Wire Accuracy

Resistance Ranges Allowable Excitation

Current Range

Pulsed Excitation

Current Compatibility

Normal Mode Rejection

Common Mode Rejection