

## REWORK SYSTEM

### QUICK 712A

#### Features:

- Password lock function, easy control.
- Auto sleeping/shut-off function.
- Digital temperature calibration, easy operation.
- Brushless fan, adjustable, stepless and wide range of air volume, suitable for various applications.
- Large air volume cooling function, prolong lifetime of heating element, protect the hot air handle.
- Closed-loop sensor, precise temperature.
- Light handle, comfortable for using.

#### Specifications:

##### Soldering part:

Power Consumption	90W
Temperature Range	50℃-500℃
Sleeping Temperature Range	50℃-250℃
Sleeping Time Range	0-250min
Temperature Stability	±2℃ (Stationary air, no load)
Ambient Temperature(Max)	40℃
Tip To Ground Potential	<2mV
Tip To Ground Resistance	<2Ω

##### Hot air part:

Power	1000W
Temperature Range	100℃-500℃
Air Volume	1-120L/min
Ambient Temperature(Max)	40℃
Temperature Stability	±2℃ (Stationary air, no load)



- Tips See p27
- Nozzles See P39