

## RS232 Commands

Command		1	3	4	5	6	7	8	9	Note
Power	OFF	S	0	0	0	1	1	0	E N	
	ON							1		
Input Source	VGA	S	0	0	0	2	1	0	E N	
	HDMI 1							1		
	HDMI 2							2		
	HDMI 3							3		
	USB 1							4		
	USB 2							5		
Brightness	0%	S	0	0	0	3	2	00	E N	
	100%							64		
	Plus							65		
	Minus							66		
Contrast	0%	S	0	0	0	4	2	00	E N	
	100%							64		
	Plus							65		
	Minus							66		
Clock	0%	S	0	0	0	5	2	00	E N	
	100%							64		
Phase	0%	S	0	0	0	6	2	00	E N	
	100%							64		
Sharpness	0	S	0	0	0	7	2	00	E N	
	100%							64		
Horizontal Position	Minus	S	0	0	0	8	1	0	E N	
	Plus							1		
Vertical Position	Minus	S	0	0	0	9	1	0	E N	
	Plus							1		
OSD Time	5secs	S	0	0	0	C	1	0	E N	5secs, 10secs, 15secs, Never
	Never							3		



<b>Zoom(Aspect Ratio)</b>		<b>S</b>	<b>0</b>	<b>0</b>	<b>1</b>	<b>4</b>	<b>0</b>		<b>E</b> <b>N</b>	
<b>Touch</b>	<b>OFF</b>	<b>S</b>	<b>0</b>	<b>0</b>	<b>1</b>	<b>6</b>	<b>1</b>	<b>0</b>	<b>E</b> <b>N</b>	
	<b>ON</b>							<b>1</b>		
<b>Freeze</b>	<b>OFF</b>	<b>S</b>	<b>0</b>	<b>0</b>	<b>1</b>	<b>7</b>	<b>0</b>		<b>E</b> <b>N</b>	
	<b>ON</b>									
<b>Auto Color</b>		<b>S</b>	<b>0</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>		<b>E</b> <b>N</b>	
<b>Auto Processing</b>		<b>S</b>	<b>0</b>	<b>0</b>	<b>2</b>	<b>1</b>	<b>0</b>		<b>E</b> <b>N</b>	
<b>Auto Ambient Light</b>	<b>OFF</b>	<b>S</b>	<b>0</b>	<b>0</b>	<b>2</b>	<b>2</b>	<b>1</b>	<b>00</b>	<b>E</b> <b>N</b>	
	<b>ON</b>							<b>01</b>		
<b>Auto Notification</b>	<b>OFF</b>	<b>S</b>	<b>0</b>	<b>0</b>	<b>2</b>	<b>3</b>	<b>1</b>	<b>00</b>	<b>E</b> <b>N</b>	
	<b>ON</b>							<b>01</b>		
<b>Serial Exclusive</b>	<b>OFF</b>	<b>S</b>	<b>0</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>E</b> <b>N</b>	
	<b>ON</b>							<b>1</b>		
<b>On Screen Menu</b>		<b>S</b>	<b>0</b>	<b>0</b>	<b>3</b>	<b>1</b>	<b>0</b>		<b>E</b> <b>N</b>	
<b>Monitor ID</b>		<b>S</b>	<b>0</b>	<b>0</b>	<b>F</b>	<b>F</b>	<b>1</b>	<b>0</b>	<b>E</b> <b>N</b>	
								<b>F</b>		
<b>Ping</b>		<b>S</b>	<b>1</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>		<b>E</b> <b>N</b>	<b>Note *</b>
<b>Query</b>		<b>S</b>	<b>1</b>	<b>0</b>	<b>5</b>	<b>1</b>	<b>2</b>	<b>00</b>	<b>E</b> <b>N</b>	<b>Note *, Note **</b>
								<b>FF</b>		
<b>Reset</b>		<b>S</b>	<b>0</b>	<b>0</b>	<b>F</b>	<b>0</b>	<b>0</b>		<b>E</b> <b>N</b>	
<b>Factory Mode</b>		<b>S</b>	<b>0</b>	<b>0</b>	<b>F</b>	<b>1</b>	<b>0</b>		<b>E</b> <b>N</b>	
<b>Engineer</b>		<b>S</b>	<b>0</b>	<b>0</b>	<b>F</b>	<b>2</b>	<b>2</b>	<b>0</b>	<b>E</b> <b>N</b>	