

Garment & Glove Sizing Chart

Worker Body Measurement: The workers actual measurements determined using a fabric measuring tape.

Oberon Coats, Bib-Overalls, Coveralls: Garment dimensions are larger than the User's measurements to allow space for movement.

Arc Flash Apparel Measuring Instructions

1. Use a Fabric Measuring Tape

Chest: Measure around the chest just under the arms and across the shoulder blades.

Waist: Measure around the natural waistline.

Height: Measure the total height of the worker. You can tape one measuring tape to a wall and have the worker stand up straight against it.


2. Select the Size

After measuring the worker select the size using the tables above. Each of these numbers represent the maximum measurement per size. Always round up and use the larger of either Chest or Waist.

3. Select the Height

All suits are sold as a Regular size. Order bib-overalls for adjustable height. Short, Tall and Extra Tall sizes are custom Made to Order. Regular Standard size is 5'10" to 6'1". Workers under 5'8" or over 6'4" need custom sizes.

SUIT MEASUREMENT GUIDE



WORKER BODY MEASUREMENTS

WORKER BODY MEASUREMENTS

SIZE	S	M	L	XL	2XL	3XL	4XL	5XL
CHEST (in)	36	39	42	46	50	54	58	62
WAIST (in)	30	33	36	40	44	48	52	56

BODY HEIGHT

WORKER BODY MEASUREMENTS

SIZE	SHORT	REGULAR	TALL	X-TALL
HEIGHT RANGE (ft)	5'7"- 5'10"	5'10"- 6'1"	6'1"- 6'4"	6'4"- 6'7"

GARMENT MEASUREMENTS

COAT MEASUREMENTS

CHEST (in)	46	49	52	56	60	64	68	72
------------	----	----	----	----	----	----	----	----

BIB-OVERALL MEASUREMENTS

WAIST (in)	34	37	40	44	48	52	56	60
------------	----	----	----	----	----	----	----	----

COVERALL MEASUREMENTS

CHEST (in)	46	49	52	56	60	64	68	72
WAIST (in)	36	39	42	46	50	54	58	62

Arc Flash Glove Measuring Guide

Step 1

Measure around the hand at the fullest part.

Step 2

Measure from the tip of the middle finger to the base of the hand.

Step 3

Use the LARGEST of these two measurements for the correct size glove.


Step 4

The number of inches/centimeters measured equals the size of the glove.

GLOVE MEASUREMENT GUIDE

A. HAND CIRCUMFERENCE

B. HAND LENGTH



GLOVE SIZING CHART

SIZE	XS	S	M	L	XL	2XL
INCHES	7	7.5	8.5-9	9.5-10	10.5-11	11.5-12

Take measurements from your dominant hand!

ARC THERMOGRAPHER GLOVE SIZING CHART

	REGULAR	REGULAR	LARGE	LARGE	X-LARGE	X-LARGE
SIZE	7	8	9	10	11	12