

## Product information No. 7 / 2022

---

Product optimisation

Repositioning of control elements  
for motorised desks TALO.YOU and  
ACTIVE.T

### **Scheduling:**

Delivery from July 2022

The position of the control under the desk top was limiting the usable surface area for motorised desks. There were isolated incidents involving unintended collision with the control element.

### **Changes:**

- The control element has been repositioned so that it is now 200 mm from the outside edge instead of 300 mm.
- The cable passes between the frame and desk top. Wiring is routed using cable clips. This avoids the risk of crushing the cable.

