

HANSER

Norman C. Lee

Understanding Blow Molding

ISBN-10: 3-446-41265-4

ISBN-13: 978-3-446-41265-1

Inhaltsverzeichnis

Weitere Informationen oder Bestellungen unter
<http://www.hanser.de/978-3-446-41265-1>
sowie im Buchhandel

Contents

Introduction to the Series	V
Preface	VII
1 Introduction to Plastic Blow Molding	1
1.1 Scope of this Book	1
1.2 Background of Plastics	1
1.2.1 History of Plastics	1
1.2.2 Polymers	2
1.2.3 Fundamental Properties	2
1.3 Plastic Polymer Types.....	3
1.3.1 Thermosets	3
1.3.2 Thermoplastics	3
1.4 References	4
2 Basic Process	5
2.1 The Principles of Blow Molding	5
2.2 Parison Formation	7
2.3 Blow Molding Development	8
3 Overview of Polymer Materials	11
3.1 Polymer Principles	11
3.2 Types of Polymers.....	11
3.3 Types of Polymerization.....	13
3.4 Resin Considerations for Blow Molding.....	15
3.4.1 Chemical End-Use Requirement.....	15
3.4.2 Physical and Processing Requirements.....	15
4 Extrusion Blow Molding.....	21
4.1 Extrusion	21
4.1.1 Mandrel and Dies.....	24
4.1.2 Wall Thickness	24
4.1.3 Blow-Up Ratio	26
4.1.4 Validation	26
4.1.5 Wall Thickness and Melt Temperature.....	26
4.2 Continuous Extrusion	27
4.2.1 Overview	27
4.2.2 Rising (Vertical Movement) Mold	28

4.2.3	Sliding (Horizontal Movement) Mold	28
4.2.4	Molds on a Rotary Wheel	29
4.3	Intermittent Method	30
5	Injection Blow Molding	33
5.1	Injection Molding Method	33
5.2	Stretch Blow Molding.....	36
6	Extrusion Blow Molding Technique	39
6.1	The Steps of the Blowing Technique.....	39
6.2	The Parison or Pre-Form	40
6.3	Essential Blow Molding Factors.....	41
6.4	Choice of the Most Suitable Resin.....	42
7	Guidelines for Selecting Industrial Blow Molding Machines	43
7.1	The Extruder	44
7.2	The Accumulator Head	45
7.3	The Press	46
7.4	Summary	47
8	Extrusion Blow Molding Advanced Systems	53
8.1	Coextrusion Blow Molding	53
8.1.1	Common Materials and Applications for Coextrusion Blow Molding	54
8.1.2	Typical Structures	55
8.1.3	Continuous Multi-Layered Coextrusion	56
8.2	Three-Dimensional Blow Molding	57
8.2.1	Three-Dimensional Blow Molding Processes	58
8.2.1.1	Suction Blow Molding	58
8.2.1.2	Parison Manipulation	59
9	Understanding Extrusion Blow Molds	61
9.1	Main Characteristics of the Mold Halves	61
9.2	Mold Materials	63
9.3	Importance of Fast Mold Cooling.....	64
9.4	The Pinch-Off.....	66
9.5	High Quality Undamaged Mold Cavity Finish	67
9.6	Effects of Air and Moisture Trapped in the Mold	68
9.7	Injection of the Blowing Air	69
9.8	Ejection of the Piece from the Mold	70
10	Understanding Injection Blow Molds	71
10.1	Tooling	71

10.2	Parison Neck Ring	71
10.2.1	Parison (Pre-Form) Cavity	72
10.2.2	Blow Mold Neck Ring	73
10.2.3	Blow Mold Cavity.....	74
10.2.4	Bottom Plug	74
10.2.5	Core Rod Assembly	75
10.2.6	Injection Manifold Systems.....	76
10.2.7	Parison (Pre-Form) Design	77
11	Finishing.....	79
11.1	Part Molding Equipment and Processing.....	79
11.2	Planning for Finishing a Blow Molded Part	79
11.2.1	Product Design.....	79
11.2.2	Mold Engineering	79
11.2.3	Process Planning	80
11.3	Removing Domes and Other Sections	83
11.3.1	Rotating Saw Blades	83
11.4	Knife Cut	83
11.4.1	The Cutting Machine – Round Parts vs. Parts with Corners	84
11.4.2	Benefits of Using a Knife Cut	85
11.5	Other Methods	85
11.6	Deburring	85
11.6.1	Common Deburring Methods	86
11.6.2	Manual Flash Removal.....	86
11.6.3	Machine Flash Removal.....	86
11.7	Clamping Needs in Extrusion Blow Molding	87
11.7.1	Blow Clamp Force	87
11.7.2	Pinch Clamp Force.....	87
11.8	Effects on the Force Required to Deflash a Part.....	88
11.9	Finishing by Machining	89
11.9.1	Drilling	90
11.10	Fixtures	90
11.11	Computerized Numerical Control	90
11.12	Robotics	91
11.13	Decoration Equipment and Processing	92
11.13.1	Surface Treatment	92
11.13.2	Spray Painting.....	95
11.13.3	Hot Stamping	95
11.13.4	Pad Printing	97
11.13.5	Screen Printing.....	99
11.13.6	Labels and Decals	101
11.13.7	In-Mold Labeling	101

12 Troubleshooting	105
12.1 Detailed Failure Analysis	107
12.1.1 Rocker Bottoms and Oval Necks	139
12.1.2 Defects Within the Blown Wall	139
12.1.2.1 Bubbles	139
12.1.2.2 Cold Spots	140
12.1.2.3 Thinning	140
12.1.2.4 Tearing	140
12.1.2.5 Cutting	141
12.1.2.6 Indented Parting Lines	141
12.1.3 Poor Bottle Surface	141
12.1.4 Curtaining and Webbing	142
12.1.5 Blowouts	143
12.1.6 Parison Curl, Stringing, Hooking, Sag, and Length Consistency ..	144
12.1.6.1 Parison Curl	144
12.1.6.2 Parison Stringing	144
12.1.6.3 Parison Hooking	144
12.1.6.4 Parison Sag	145
12.1.6.5 Parison Length Inconsistency	145
12.1.7 Foreign Matter in the Melt	145
12.1.7.1 Look for Exterior Sources of Contamination First	146
12.1.7.2 Degraded Resin – Many Sources	146
12.1.7.3 Culprit – Man or Machine?	147
12.1.8 Die Lines or Streaking in the Parison	147
12.1.9 Shrinkage	148
12.1.10 Causes of Stress Cracking	148
12.1.10.1 Environmental Stress Cracking	148
12.1.10.2 Solvent Stress Cracking	149
12.1.10.3 Mechanical Stress Cracking	149
12.1.11 Heat – Too Much or Too Little and What to Do About It	150
12.1.11.1 Instrument Recalibration	151
12.1.12 Surging	152
12.1.13 Sharkskin	152
12.1.14 Screw Wear Affects Performance	155
12.1.14.1 Inspection Rollers	155
12.1.14.2 Diameters	155
12.1.14.3 Depths	156
12.1.14.4 Concentricity and Straightness	157
12.1.14.5 Hardness	157
12.1.14.6 Finish and Coating Thickness	158
12.1.14.7 Screw Manufacturing Tolerances	159

12.1.15 Barrel Inspection	159
12.1.15.1 Inside Diameters	159
12.1.15.2 Straightness and Concentricity	159
12.1.15.3 Barrel Hardness	160
12.1.15.4 Barrel Specifications	160
12.1.16 Detecting Container Leakage	161
Appendix	163
Plastics Acronyms	163
Index	173