
Installation instructions





750023EJ

Mazda BT50

12/11 >>




SCAN FOR LATEST **INSTRUCTIONS**
















Reference:


The following information must be reviewed before beginning the assembly:

The installation instructions are to be thoroughly read.


The installation should be carried out by qualified personnel with the relevant technical knowledge. The vehicle manufacturers' current technical notices and information on retrofitting must be followed. The removal and replacement instructions found in the current repair manuals must be followed.


It must be ensured that the vehicle is technically suitable for the installation of a trailer hitch.








TOOLS






























1	ye	\triangleleft
2	bk	1 3 2 4 R
3	wh	=
4	gn	
5	bu	
6	rd	Stop
7	bn	

9	bk	wh	gy	gn	rd	bu	ye	bn	pu	or	no
GB	black	white	grey	green	red	blue	yellow	brown	purple	orange	not occupied













12 OPTION 2





750023d210519 9 / 17





















Vehicle harness to PDC module

16 OPTION 1
















18 OPTION 2





750023d210519 12 / 17


19 OPTION 2














23 CHECK ALL LIGHTING FUNCTIONS




23 CHECK ALL LIGHTING FUNCTIONS




24 CHECK BULB OUT DETECTION






26



750023d210519 15 / 17






Subject to change in terms of construction, equipment and colour, and may contain errors.

The information and illustrations are non-binding.

Status LED for self-diagnosis



750023d210519 16 / 17