
Installation instructions








750112

MERCEDES BENZ Sprinter W907 / W910

06/18 >>















Reference:

The following information must be reviewed before beginning the assembly:

The installation instructions are to be thoroughly read.

The installation should be carried out by qualified personnel with the relevant technical knowledge.


The vehicle manufacturers' current technical notices and information on retrofitting must be followed.

The removal and replacement instructions found in the current repair manuals must be followed.


It must be ensured that the vehicle is technically suitable for the installation of a trailer hitch.

750112-060619B8 1 / 18


OVERVIEW



750112-060619B8 2 / 18





TOOLS







Be careful! If you don't disconnect the battery, the vehicle will show a lot of error messages in instrument panel!

















In case of wrong pin insert:














750112-060619B8 7 / 18























1	ye	\Diamond
2	bk	1 3 2 4 (R)
3	wh	÷
4	gn	\Diamond
5	bu	
6	rd	Stop
7	bn	


9	bk	wh	gy	gn	rd	bu	ye	bn	pu	or	no
GB	black	white	grey	green	red	blue	yellow	brown	purple	orange	not occupied





















17 W907




18 W910



750112-060619B8 14 / 18


19 OPTIONAL








Trailer Brake Preparation






















21 CODING


Optional only for PDC deactivation



22 CHECK ALL LIGHTING FUNCTIONS





23 CHECK BULB OUT DETECTION



750112-060619B8 | 16 / 18










Subject to change in terms of construction, equipment and colour, and may contain errors.

The information and illustrations are non-binding.

750112-060619B8 17 / 18

Status LED for self-diagnosis



750112-060619B8 18 / 18