



GV2ME●●

GV2AF01 / GV2AF3  
LC1K●● / LC1D●●

1,7 N.m  
15 lb.in

1 N.m 7 lb.in  
1,7 N.m 15 lb.in  
2,5 N.m 20 lb.in

LC1K 1 N.m 7 lb.in  
LC1D9/12/18 1,7 N.m 15 lb.in  
LC125/32 2,5 N.m 20 lb.in

Ø 6 mm

www.schneider-electric.com/site/home

1672546

GV1G09 GV2G4●●

GV2G05 GV2G2●●

GV1L3

GVAM11

Click!

Click!

TEST

STOP

≤ Ø 3 mm  
1/16 inch

Ø 3 mm  
1/8 inch

	mm AWG	mm in	N.m lb-in
x1 x2	1...6 18...10		1,7
x1 x2	6...10 18...10	3/8	15
x1 x2	1...4 18...10		

Schneider Electric Industries SAS  
35, rue Joseph Monier  
92506 Rueil Malmaison  
France

www.schneider-electric.com  
W9 1645571 0211-08

GV2ME●●  
04 - 2016

**⚠ ⚠ DANGER / 危险**

**HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH**

Disconnect all power before servicing equipment.  
Failure to follow these instructions will result in death or serious injury.

电击、爆炸或电弧闪光危险  
在此电力设备上进行操作时，请先断开所有电源  
不遵循上述规定将可能导致人员伤亡。

