

Stick



ON - OFF 2

CONNECT

220 V~
240

Ø50

DIM PHASE CUT

DIM DALI

- FOLLOW CONNECTION DIAGRAM OF THE POWER SUPPLY

ADJUST LENGTH

ON

ADJUST

Stick Base



ON - OFF 3a

DIM PHASE CUT

DIM DALI

- FOLLOW CONNECTION DIAGRAM OF THE POWER SUPPLY

CONNECT

220 V~
240

DIM DALI 3b

CONNECT

D1- D2+ L N

220 V~
240

- FOLLOW CONNECTION DIAGRAM OF THE POWER SUPPLY

ADJUST LUMINAIRE HEIGHT

LOCK

Stick 48V



click !

CHANGE POSITION

NO

ADJUST LENGTH

ON

ADJUST

Stick 24V



ATTEND POLARITY

LOCK

ADJUST LENGTH

ON

ADJUST

CORD ACCESSORY

ADJUST

