

## **RF420420** MOTOR PROTECTION RELAY, PHASE FAILURE/SINGLE-PHASE SENSITIVE. THREE-POLE (THREE-PHASE), MANUAL OR AUTOMATIC RESETTING, 250...420A



Product designation			RF420 Motor protection
Product type designation			relay
General characteristics			
Number of poles		Nr.	3
Overvoltage category			III
Pollution degree			3
Frontal IP degree			IP20
Type of release			Thermal
Protection fuse			
	gG (IEC)	А	630
	aM (IEC)	А	500
	K5 (UL)	А	800
Phase failure detection			yes
Reset mode			Manual or
			automatic
Power circuit characteristics			
Rated insulation voltage Ui IEC/EN		V	1000
Rated impulse withstand voltage Uimp		kV	6
Rated operational voltage		V	690
Operational frequency			
	min	Hz	50
	max	Hz	60
Operational current le			
	Operational current min	А	250
	Operational current max	А	420
Tripping class			10A
Test Button			yes
Trip indicator			yes
Terminals			-
			screw and flat
	type		washer
	screw		M10
	width	mm	25
	tool		Bar 18mm
Tightening torque for terminals			
	min	Nm	35
	max	Nm	35
	min	Ibin	25.9
	max	Ibin	25.9
Auxiliary circuit characteristics			
Auxiliary contacts			
	NO	Nr.	1
	NC	Nr.	1
Auxiliary Rated insulation voltage Ui IEC/EN		V	690

RF420420

The characteristics described in this document are subject to updates or modifications at any time. The descriptions, technical and functional information, illustrations and instructions in this brochure are purely illustrative, and are consequently not contractually binding



## **RF420420** MOTOR PROTECTION RELAY, PHASE FAILURE/SINGLE-PHASE SENSITIVE. THREE-POLE (THREE-PHASE), MANUAL OR AUTOMATIC RESETTING, 250...420A


Auxiliary Rated impulse withstand voltage Uimp	kV	6
Auxiliary Rated operational voltage	V	690
Operating current AC15	v	000
24V	А	3
120V	A	3
240V	A	1.5
380V	А	0.95
480V	А	0.75
500V	А	0.72
600V	Α	0.6
Operating current DC13		
125V	А	0.11
600V	Α	0.22
IEC Conventional free air thermal current Ith	Α	10
Terminals		
Auxiliary circuit type		screw and washer
Auxiliary circuit screw		M3,5
Auxiliary circuit width	mm	8
Auxiliary circuit tool		Phillips 2
Conductor section		
Auxiliary circuit Flexible w/o lug max	mm²	2.5
Auxiliary circut Flexible c/w lug max	mm²	2.5
Tightening torque for terminals		
Auxiliary circuit min	Nm	0.8
Auxiliary circuit max	Nm	1
Auxiliary circuit min	Ibin	0.59
Auxiliary circuit max	Ibin	0.74
UL/CSA and IEC/EN 60947-5-1 designation		B600-R300
Ambient conditions		
Operating temperature	° <b>^</b>	25
min	°C ℃	-25 60
Storage temperature max	U	00
min	°C	-50
max	°C	70
Compensation temperature	0	10
min	°C	-20
max	°C	60
Max altitude	m	3000
Mechanical features		
Operating position		
normal		Vertical plan
allowable		±30°
Fixing		Screw
Weight	g	2460
UL technical data		
Full-load current (FLA) for three-phase AC motor		
at 480V	А	420
at 600V	А	420
Dimensions		
Wiring diagrams		

RF420420

RF420420



MOTOR PROTECTION RELAY, PHASE FAILURE/SINGLE-PHASE SENSITIVE. THREE-POLE (THREE-PHASE), MANUAL OR AUTOMATIC RESETTING, 250...420A



Compliance		
-	CSA C22.2 n° 14	
	IEC/EN 60947-1	
	IEC/EN 60947-4-1	
	UL508	
Certifications		
	cULus	
	EAC	
ETIM classification		
		= 0 0 0 0 1 0 0

**ETIM 8.0** 

EC000106 -Thermal overload relay