

## PRODUCT SPECIFICATION SHEET

### PRODUCT INFORMATION

<b>Style:</b>	<b>Heavy Weight Sleeve</b>		
<b>Sizing:</b>	<u>Part #</u>	<u>Length</u>	<u>Bottom</u>
	S-11HR	19"	Hemmed
	S-14HR	16"	Knit Wrist
	S-15HR	14"	Knit Wrist
<b>Registered Brand Name:</b>	Jomac®		
<b>Classification:</b>	Heat Resistant		



### PRODUCT DESCRIPTION

<b>Description:</b>	Heavy Weight Sleeve with Elastic top
<b>Color:</b>	Natural White
<b>Material:</b>	Cut & Sewn Terry Loop-out
<b>Weight:</b>	Heavy Weight
<b>Cuff:</b>	Knit Wrist / Elastic Top
<b>Heat Resistance:</b>	Protects Up to 350°F
<b>Sold by:</b>	Dozen Pieces
<b>Packaging (Inner Pack):</b>	12 Pieces
<b>Packaging (Case Pack):</b>	72 Pieces

### WASHING INSTRUCTIONS

Machine wash in warm water with mild detergent or soap for 10-15 minutes. Water temperature should not exceed 160°F (71°C). Rinse in cold water. Tumble dry for 10-15 minutes, not exceeding 150°F (67°C). Terry products may require additional drying time. Do not use bleach or dry cleaning solution.

### CAUTION

The degree of heat resistance a glove may offer is directly related to the duration of exposure and weight of the object being handled.

Wells Lamont Industrial 6640 W Touhy Ave Niles IL 60714  
Toll-Free 1.800.247.3295 Fax 1.847.470.1026 www.wellslamontindustrial.com

KM 03/17