




✉ 2621 Merced Avenue El Monte, CA 91733
 ☎ 626.443.7456 | FAX: 626.401.2715
 🌐 transgo.com E-mail: sales@transgo.com

PRODUCT UPGRADE GM 6T30, 6T40, 6T45 GEN1


NO REAMING, NO SPECIAL TOOLS

Easy install with all drop-in components including **new TCC regulator valve**, pressure regulator valve and AFL valve assemblies, plus pressure switch components to save a TEHCM.


GEN1 2007-on units with pressure switches



GEN1 units are identified by the existence of (4) pressure switches in the TEHCM.



When you split the valve body, GEN1 units have no pulse dampeners.



SK 6T40-A Upgraded!

Shift Kit®

6T30, 6T40, 6T45 GEN1 2007-on with pressure switches

Features:

- Drop-in components to address ratio and solenoid performance codes

Corrects/Prevents/Reduces:

- Erratic high pressure condition resulting in broken components
- Codes: P0751, P0752, P0776, P0777, P0796, P0797, P2714, P2715, P2723, P2724

Includes:

- NEW! Drop-in TCC regulator valve
- Drop-in pressure regulator valve
- Drop-in actuator feed limit valve assembly
- Pressure switch components to save a TEHCM

ALSO AVAILABLE SEPARATELY



PSR-5

Pressure Switch Repair Kit
6T70, 6T75 GEN1 2007-on

Features:

- A real money saver! No need to buy and program a new TEHCM

Corrects/Prevents/Reduces:

- Damaged pressure switches that leak and set pressure codes

Includes:

- Replacement pressure switch diaphragms and seals

ENGINEERED FOR PERFORMANCE.
DESIGNED FOR DURABILITY.

©TransGo. All rights reserved. TransGo®, Shift Kit®, SK® and Reprogramming Kit™ are registered and licensed trademarks.

