## NOTES:

- 1. BE SURE INDEXING PINS ARE INSTALLED AND ORIENTED TO ACCOMODATE YOUR DESIRED MOUNTING
- 2. THE HANDLE/STEM REPAIR KIT FOR THIS MODEL IS: 5830HST.
- 3. THE VALVE REPAIR KIT FOR THIS MODEL IS: 5800VRKT.

