

A white, rectangular motor starter unit. It features a green circular stop button with a vertical line in the center, and a red circular start button with a curved arrow. Below the buttons, there is a label that reads "MOTOR STARTER". The unit has a small brass-colored screw on top and two grey mounting tabs on the sides.

Technical drawing showing the front and top views of a rectangular block with a trapezoidal cutout on the left side.

Front View Dimensions:

- Top width: $A = 5.51"$
- Bottom width: $B = 4.72"$
- Height: $C = 6.10"$
- Depth: $D = 7.20"$

Top View Dimensions:

- Width: $E = 5.91"$
- Depth: $F = 3.46"$

Cutout Dimensions:

- Top width: $G = 6.10"$
- Bottom width: $H = 5.31"$

Technical drawing of the 'K' type machine tool head. The drawing includes three views: a side view (left), a front view (bottom), and a top view (right). Dimensions are provided in millimeters (mm). The side view shows a total width of 200mm and a height of 100mm. The front view shows a total width of 200mm and a height of 100mm. The top view shows a total width of 200mm and a height of 100mm. The drawing also includes a detail view of the top surface, showing a central hole with a diameter of $\phi 12$ and a distance of 50mm from the center to the edge. The drawing is labeled 'K' and 'K'.



UL **CSA**
LISTED



UL **CSA**
LISTED

TA7D0964