

Zebra[®] Hardness Testing Sticks

Prevent Coolant Pudding, Foam, and Rust

- Easy to use
- · Dip in the coolant to match colors
- Results in 3 seconds
- 50 sticks per bottle will last one year per sump
- Non-hazardous

Part Number XWT50

Description

A must for every shop

Metalworking fluid is formulated with water that lacks any minerals. However, tap water contains many. And, since your coolant only accumulates more minerals over time due to evaporation (more than 5% per day by volume), water hardness, if not addressed, can lead to problems.

Coolant Split: When a coolant split occurs, you will notice that there is a layer of pudding-like coolant floating on top of your sump. Your coolant concentrate is no longer in solution, and no longer a good tool for cooling or lubricating.



Hardness Testing Sticks 0-1000 ppm calcium carbonates anesium

Grease Formation: Coolant, and any tramp oils forming on its surface, may turn into a grease layer. This layer is impossible to pick up using an oil skimmer and can block filters and hoses.

Gummy and Soapy Residues: These may form inside your machine and on all surfaces coolant comes in contact with. Machine equipment and parts integrity may be affected.

Rust: Can damage machine interior and cause premature part corrosion.

Foaming: This causes flooding of your machine sump as well as a rougher environment for oil skimming, and is caused by LOW hardness.

To avoid hardness related issues, check with your coolant supplier to verify what hardness range your coolant can withstand and keep it there. Many suppliers also carry a line of water softening or hardening agents, which you can add to the sump for correction. If water hardness poses a constant problem, consider an RO (reverse osmosis) water suppy.

Zebra Skimmers Corporation 27000 Richmond Rd, Unit 1 Solon. OH 44139 www.ZebraSkimmers.com

Toll-Free: 888-249-4855 Phone: 440.349.0141 Fax: 440 349 1211 © Zebra Skimmers Corp. All rights reserved.







