



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13810748 - 2016 JLG 4069LE Electric Scissor Lift



Item Details:

- Features: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box
- Meter Reading: 404 Hours
- Serial # : 0200256802
- Inspection Completed: 8/21/25

Shipping Details:

- Location California (Yolo County)
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0200256802	
Hour Meter / Odometer	404 hrs	
Paint	No visible damage	
Body Panels	Battery compartment door damaged	
Steps/Ladders		
Basket / Safety Railing	Some pins are missing	
General Appearance #1		
General Appearance #2		


General Appearance #3		
General Appearance #4		
General Appearance #5		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	
Safety #1		

Control Station Ground		
Item	Assessment	Photo
Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Ground #1		

Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.


Item	Assessment	Photo
Control Console	No visible damage or missing components	 A photograph of the control console on a yellow JLG scissor lift. The console is mounted on the side of the lift and features a black control panel with various buttons and a red emergency stop button. The JLG logo is visible on the yellow background.
Emergency Shut Off Switch	Operational	 A close-up photograph of the emergency shut off switch, which is a red button with a yellow base, mounted on the control console.
Upper Function Controls	☆☆☆☆	 A photograph of the upper function controls, showing a joystick and several buttons on the control console.
Limited Function Check	The main components are in place and operational as noted.	
Control Station Upper #1		 A photograph of the control station upper #1, showing the control console and the scissor lift mechanism.

Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	48 Volts	
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included	
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		
Electrical Operating System #2		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.


Item	Assessment	Photo
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1		 A close-up photograph of a black hydraulic cylinder mounted on a white metal frame. A blue label with white text is visible, reading "MAX 3700 lbs 1678 kg" with a downward arrow. An "IRON PLANET" watermark is in the bottom right corner.
Hydraulics #2		 A close-up photograph of a black hydraulic cylinder mounted on a yellow metal frame. A blue label with white text is visible, reading "MAX 3700 lbs 1678 kg" with a downward arrow. An "IRON PLANET" watermark is in the bottom right corner.
Hydraulics #3		 A photograph of a hydraulic pump and valve assembly mounted on a yellow metal frame. The assembly includes a black pump motor, various hoses, and a control valve. An "IRON PLANET" watermark is in the bottom right corner.
Hydraulics #4		 A close-up photograph of a hydraulic cylinder with a silver-colored body and black hoses, mounted on a yellow metal frame. An "IRON PLANET" watermark is in the bottom right corner.
Hydraulics #5		 A photograph of a hydraulic valve assembly with multiple ports and hoses, mounted on a yellow metal frame. An "IRON PLANET" watermark is in the bottom right corner.
Hydraulics #6		 A photograph of a hydraulic valve assembly with multiple ports and hoses, mounted on a yellow metal frame. An "IRON PLANET" watermark is in the bottom right corner.

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Brake System	★★☆☆ The brake system functioned, stopping and holding the machine.	
Steering Linkage	★★☆☆	
Frame Condition	★★☆☆	
Scissor Linkage	★★☆☆	
Platform Condition	★★☆☆	
Platform Extension	★★☆☆	

Left Front Tire	Chunks missing	
Left Rear Tire	Cracks	
Right Rear Tire	Cracks	
Right Front Tire	Cracks	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		

Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		
Chassis #8		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved