



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13810982 - 2016 Skyjack SJ61T 4WD Diesel Telescopic Boom Lift



Item Details:

- Features: 61 ft Max Platform Height, Power to Platform, 2016 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 385/65D19.5 Tires
- Meter Reading: 4,250 Hours
- Serial # : 97001865
- Inspection Completed: 8/26/25

Shipping Details:

- Location Texas (Tarrant County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		 A photograph showing the left front corner of the red Skyjack SJ61T boom lift. The lift is parked on a gravel lot, and its telescopic boom is extended upwards. The IronPlanet logo is visible in the bottom right corner of the photo.
Picture, Left Rear Corner		 A photograph showing the left rear corner of the red Skyjack SJ61T boom lift. The lift is parked on a gravel lot, and its telescopic boom is extended upwards. The IronPlanet logo is visible in the bottom right corner of the photo.
Picture, Right Rear Corner		 A photograph showing the right rear corner of the red Skyjack SJ61T boom lift. The lift is parked on a gravel lot, and its telescopic boom is extended upwards. The IronPlanet logo is visible in the bottom right corner of the photo.
Picture, Right Front Corner		 A photograph showing the right front corner of the red Skyjack SJ61T boom lift. The lift is parked on a gravel lot, and its telescopic boom is extended upwards. The IronPlanet logo is visible in the bottom right corner of the photo.

Serial Number / VIN	97001865	
Hour Meter / Odometer	4250 hrs	
Paint		
Body Panels	Hydraulic compartment door damaged	
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		
General Appearance #2		

General Appearance #3		
General Appearance #4		


Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Swing Brake	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	
Safety #1		
Safety #2		

Control Station Ground		
Item	Assessment	Photo
Function Controls	★★★★☆	
Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Ground # 1		

Control Station

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Safety Control Foot Switch	★★★★☆ Operational	
Function Controls	★★★★☆	
Engine Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Control Station #1		

Engine		
Item	Assessment	Photo
Engine #1		
Engine #2		
Emission Label		
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	


Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	After jump starting, the engine ran.	

Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	12 Volts	
Battery Condition	Weak or under-charged	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included	
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Front Final Drive	★★★★☆	
Left Front Drive Motor	★★★★☆	
Left Rear Final Drive	★★★★☆	
Left Rear Drive Motor	★★★★☆	
Right Rear Final Drive	★★★★☆	
Right Rear Drive Motor	★★★★☆	

Right Front Final Drive	★★★★☆	
Right Front Drive Motor	★★★★☆	
Front Center Drive Motor	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulic)	★★★★☆	
Steering Cylinders	★★★★☆	
Boom Lift Cylinder	★★★★☆	

Secondary Boom Cylinder	★★★★☆	
Boom Extension Cylinder	★★★★☆	
Basket Tilt Cylinder	★★★★☆	
Basket Rotator Motor	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		

Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		

Chassis		
Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Chassis #7		
Chassis #8		
Chassis #9		
Chassis #10		
Steering Linkage	★★☆☆	
Frame Condition	★★★★	
Left Front Tire	No visible defects	

Left Rear Tire	No visible defects	
Right Rear Tire	No visible defects	
Right Front Tire	No visible defects	
Wheel Condition	No visible damage or missing components	
Turntable Bearing	★★★★☆	
Bottom Covers		
Swing Motor	★★★★☆	

Hydraulic Center Swivel	★★★★☆	
Boom Condition	★★★★☆	
Left Side of Boom		
Right Side of Boom		
Boom Wear Guides	★★★★☆	
Cable Tray Ladder		
Work Basket		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved