



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13811378 - 2017 JLG 1250AJP 4WD Diesel Articulating Boom Lift



Item Details:

- Features: 125 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, Onboard Generator, 2017 US EPA Label, CARB Compliant, Deutz TCD 2.9 L4 4 Cylinder 74 hp 2.9 L Diesel Engine, Positive Air Shutoff, 445/50D710 Foam-Filled Tires
- Meter Reading: 4,711 Hours
- Serial # : 0300233354
- Inspection Completed: 8/5/25

Shipping Details:

- Location Alberta
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Buyer MUST Call 48 Hours in Advance of Pickup, Buyer MUST Self Load

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.



Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected


General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		


Serial Number / VIN	0300233354	
Hour Meter / Odometer	4711 hrs	
Paint	Other unknown material Adhesive from decals	
Body Panels	Engine compartment door damaged, Battery compartment door damaged, Hydraulic compartment door damaged	
Basket / Safety Railing	Front railing damaged	
General Appearance #1		
General Appearance #2		
General Appearance #3		


General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		
General Appearance #9		
General Appearance #10		

General Appearance #11		
General Appearance #12		
General Appearance #13		
General Appearance #14		
General Appearance #15		
General Appearance #16		
General Appearance #17		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Inoperable	
Swing Brake	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	
ANSI Guidelines	Yes	

Control Station Ground		
Item	Assessment	Photo
Function Controls	★★★★☆	
Oil Pressure	No oil pressure indicator	
Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Ground # 1		

Control Station		
Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Control Console	No visible damage or missing components Lower housing needs to be bolted back on	
Emergency Shut Off Switch	Operational	
Safety Control Foot Switch	★★★★☆ Operational	
Function Controls	★★★★☆	
Engine Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Control Station #1		
Control Station #2		

Engine		
Item	Assessment	Photo
Emission Label		
Blow-by (subjective visual observation)	Visible	
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	


Cooling System Leaks	No dripping leaks	
Onboard Generator	Not operationally checked	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	
Engine #1		
Engine #2		

Drivetrain


Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.


Item	Assessment	Photo
Left Front Final Drive	★★★★☆	
Left Front Drive Motor	★★★★☆	
Left Rear Final Drive	★★★★☆	
Left Rear Drive Motor	★★★★☆	
Right Rear Final Drive	★★★★☆	
Right Rear Drive Motor	★★★★☆	

Right Front Final Drive	☆☆☆☆	
Right Front Drive Motor	☆☆☆☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulic)	★★★★☆	
Steering Cylinders	★★★★☆	
Boom Lift Cylinder	★★★★☆	

Secondary Boom Cylinder	★★★★☆	
Boom Extension Cylinder	★★★★☆	
Jib Cylinder	★★★★☆	
Basket Tilt Cylinder	★★★★☆	
Basket Rotator Motor	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		

Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		
Hydraulics #7		
Hydraulics #8		


Hydraulics #9		
Hydraulics #10		
Hydraulics #11		
Hydraulics #12		
Hydraulics #13		
Hydraulics #14		
Hydraulics #15		

Hydraulics #16		
Hydraulics #17		
Hydraulics #18		

Chassis		
Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Brake System	★★★★☆ The brake system functioned, stopping and holding the machine.	
Left Front Tire	Cracks	
Left Rear Tire	Cracks, Chunks missing, Tears	
Right Rear Tire	Cracks, Chunks missing, Tears	
Right Front Tire	Cracks	

Wheel Condition	No visible damage or missing components	
Turntable Bearing	★★★★☆	
Bottom Covers		
Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Condition	★★★★☆	
Left Side of Boom		

Right Side of Boom		
Boom Wear Guides	★★★★☆	
Jib Condition	★★★★☆	
Cable Tray Ladder		
Work Basket		
Extendable Axles	Operational	
Chassis #1		

Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		
Chassis #8		

Chassis #9		
Chassis #10		
Chassis #11		
Chassis #12		
Chassis #13		
Chassis #14		
Chassis #15		

Chassis #16		
Chassis #17		
Chassis #18		
Chassis #19		
Chassis #20		
Chassis #21		
Chassis #22		

Chassis #23		
Chassis #24		
Chassis #25		
Chassis #26		
Chassis #27		
Chassis #28		
Chassis #29		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved