



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13869093 - 2018 Genie S40 4WD Diesel Telescopic Boom Lift



Item Details:

- Features: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2018 US EPA Label, Deutz D 2.9 L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Tires
- Meter Reading: 2,504 Miles
- Serial # : S40H-26324
- Inspection Completed: 9/3/25

Shipping Details:

- Location Illinois (Grundy County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	S40H-26324	
Hour Meter / Odometer	2504 mi	
Paint	No visible damage, Work basket rusted.	
Body Panels	No visible damage or missing components	
Steps/Ladders		
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Swing Brake	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	

Control Station Ground		
Item	Assessment	Photo
Gauges	Operational	
Function Controls	★★★★☆	
Oil Pressure	The gauge registers in the operating range.	
Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Control Station		
Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Safety Control Foot Switch	☆☆☆☆	
Function Controls	☆☆☆☆	
Engine Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Emission Label		
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	

Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	
Engine #1		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Front Final Drive	★★★★☆	
Left Front Drive Motor	★★★★☆	
Left Rear Final Drive	★★★★☆	
Left Rear Drive Motor	★★★★☆	
Right Rear Final Drive	★★★★☆	
Right Rear Drive Motor	★★★★☆	

Right Front Final Drive	☆☆☆☆	
Right Front Drive Motor	☆☆☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulic)	★★★★☆	
Steering Cylinders	★★★★☆	
Boom Lift Cylinder	★★★★☆	

Secondary Boom Cylinder	★★★★☆	
Boom Extension Cylinder	★★★★☆	
Basket Tilt Cylinder	★★★★☆	
Basket Rotator Motor	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		

Chassis		
Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Brake System	★★★★☆ The brake system functioned, stopping and holding the machine.	
Left Front Tire	No visible defects	
Left Rear Tire	No visible defects	
Right Rear Tire	No visible defects	

Right Front Tire	No visible defects	
Wheel Condition	No visible damage or missing components	
Turntable Bearing	★★★★☆	
Bottom Covers		
Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Condition	★★★★☆	

Left Side of Boom		 A photograph showing the left side of the blue telescopic boom of a Genie S40 4WD lift. The boom is extended, and the 'S40' and '4x4' markings are visible. An 'IRON PLANET' watermark is present in the bottom right corner.
Right Side of Boom		 A photograph showing the right side of the blue telescopic boom. The boom is extended, and the '4x4' marking is visible. An 'IRON PLANET' watermark is present in the bottom right corner.
Boom Wear Guides	★★★★☆	 A close-up photograph of the boom wear guides, showing the blue painted metal structure and the wear-resistant components. An 'IRON PLANET' watermark is present in the bottom right corner.
Cable Tray Ladder		 A photograph of the cable tray ladder, showing the blue structure and the black cables running along it. The '4x4' marking is visible on the boom. An 'IRON PLANET' watermark is present in the bottom right corner.
Work Basket		 A photograph of the work basket, showing the blue structure and the platform. The '4x4' marking is visible on the boom. An 'IRON PLANET' watermark is present in the bottom right corner.
Chassis #1		 A close-up photograph of the chassis, showing the blue structure and the hydraulic components. An 'IRON PLANET' watermark is present in the bottom right corner.
Chassis #2		 A photograph of the chassis, showing the blue structure and the platform. The 'S40' and '4x4' markings are visible. An 'IRON PLANET' watermark is present in the bottom right corner.

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved