



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #13810614 - 2017 Skyjack SJ843TH Telehandler



### Item Details:

- Features: Enclosed Cab, 43 ft Max Lift Height, 8000 lb Max Lift Capacity, 2017 US EPA Label, CARB Compliant, 48 in Forks, Auxiliary Hydraulic Plumbing, 13.00-24 Tires
- Meter Reading: 0 Miles
- Serial # : 87110702
- Inspection Completed: 8/31/25

### Shipping Details:

- Location Ontario
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

# Inspection Report


**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

## **Inspection Ratings Key**

|       |                                                                                   |
|-------|-----------------------------------------------------------------------------------|
| ★★★★  | Limited use or recently replaced. Free of visible wear or defects.                |
| ★★★☆☆ | Performs within the tolerances expected for age and type of item                  |
| ★★☆☆☆ | Although performing, shows indication of needing repair or replacement            |
| ★☆☆☆☆ | Needs immediate repair/replacement. Requires work if it is to perform as expected |


## **General Appearance**

| Item                        | Assessment | Photo                                                                                |
|-----------------------------|------------|--------------------------------------------------------------------------------------|
| Spin                        |            |                                                                                      |
| Picture, Left Front Corner  |            |   |
| Picture, Left Rear Corner   |            |  |
| Picture, Right Rear Corner  |            |  |
| Picture, Right Front Corner |            |  |

|                           |          |                                                                                      |
|---------------------------|----------|--------------------------------------------------------------------------------------|
| Serial Number / VIN       | 87110702 |     |
| Hour Meter / Odometer     | 0 mi     |    |
| v3 General Appearance # 1 |          |    |
| v3 General Appearance # 2 |          |   |
| v3 General Appearance # 3 |          |  |
| v3 General Appearance # 4 |          |  |
| v3 General Appearance # 5 |          |  |

| Control Station    |            |                                                                                      |
|--------------------|------------|--------------------------------------------------------------------------------------|
| Item               | Assessment | Photo                                                                                |
| Control Station #1 |            |    |
| Control Station #2 |            |    |
| Control Station #3 |            |   |
| Control Station #4 |            |  |
| Control Station #5 |            |  |
| Control Station #6 |            |  |

|                        |                                                            |                                                                                   |
|------------------------|------------------------------------------------------------|-----------------------------------------------------------------------------------|
| Control Station #7     |                                                            |  |
| Limited Function Check | The main components are in place and operational as noted. |                                                                                   |

| Engine                 |                                   |                                                                                      |
|------------------------|-----------------------------------|--------------------------------------------------------------------------------------|
| Item                   | Assessment                        | Photo                                                                                |
| Engine                 | 2017 US EPA Label, CARB Compliant |                                                                                      |
| v2 Engine # 1          |                                   |    |
| v2 Engine # 2          |                                   |    |
| v2 Engine # 3          |                                   |   |
| v2 Engine # 4          |                                   |  |
| Limited Function Check | The engine started and ran.       |                                                                                      |

| Drivetrain             |                                 |                                                                                    |
|------------------------|---------------------------------|------------------------------------------------------------------------------------|
| Item                   | Assessment                      | Photo                                                                              |
| Limited Function Check | The drivetrain was operational. |                                                                                    |
| Drivetrain #1          |                                 |  |
| Drivetrain #2          |                                 |  |

| Hydraulics             |                                       |                                                                                      |
|------------------------|---------------------------------------|--------------------------------------------------------------------------------------|
| Item                   | Assessment                            | Photo                                                                                |
| Limited Function Check | The hydraulic system was operational. |                                                                                      |
| Hydraulics #1          |                                       |    |
| Hydraulics #2          |                                       |    |
| Hydraulics #3          |                                       |   |
| Hydraulics #4          |                                       |  |
| Hydraulics #5          |                                       |  |
| Hydraulics #6          |                                       |  |

|               |  |                                                                                    |
|---------------|--|------------------------------------------------------------------------------------|
| Hydraulics #7 |  |   |
| Hydraulics #8 |  |  |
| Hydraulics #9 |  |  |

## Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item       | Assessment | Photo                                                                                |
|------------|------------|--------------------------------------------------------------------------------------|
| Chassis #1 |            |    |
| Chassis #2 |            |    |
| Chassis #3 |            |   |
| Chassis #4 |            |  |
| Chassis #5 |            |  |
| Chassis #6 |            |  |

|             |  |                                                                                      |
|-------------|--|--------------------------------------------------------------------------------------|
| Chassis #7  |  |     |
| Chassis #8  |  |    |
| Chassis #9  |  |    |
| Chassis #10 |  |   |
| Chassis #11 |  |  |
| Chassis #12 |  |  |
| Chassis #13 |  |  |

**Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983**

IronPlanet , Inc. © 2012 All Rights Reserved