



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13810914 - 2016 SkyTrak 6042 Telehandler



Item Details:

- Features: Enclosed Cab, Air Conditioner, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Manual Coupler
- Meter Reading: 5,140 Hours
- Serial # : 0160075790
- Inspection Completed: 8/21/25

Shipping Details:

- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0160075790	
Paint	Damage	
Body Panels	Has rust on some of the panels . Counterweight is busted on the back.	
Steps	Cab step bent	
Hand Rails	No visible damage or missing components	
Exterior Lights	1 Inoperable / damaged / missing	
General Appearance #1		


General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		

General Appearance #9		
General Appearance #10		
General Appearance #11		
General Appearance #12		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station		
Item	Assessment	Photo
Seat/Armrests	Operator seat cushion damaged	
Glass	Windshield has a chip in it	
Mirrors	Missing one	
Cab Door	No visible damage or missing components	
Steering Control	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	★★★★☆	
Load Charts	Chart book in cab	
Engine Oil Pressure	The gauge registers in the operating range.	
Warning Lights	Operational, Has a light flashing	
Gauges	Operational, Screen is hard to see	
Hour Meter / Odometer	5140 hrs	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Control Station #6		
Control Station #7		

Control Station #8		
Control Station #9		

Engine		
Item	Assessment	Photo
A/C Compressor	Operational	
Blow-by (subjective visual observation)	Can not get video	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	

Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	
Engine #1		
Engine #2		
Engine #3		
Engine #4		
Engine #5		

Engine #6		
Engine #7		
Engine #8		
Engine #9		
Engine #10		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Front Axle Oscillating Pin	★★☆☆	
Rear Drive Axle	★★☆☆	
Rear Axle Oscillating Pin	★★☆☆	

Final Drives	☆☆☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked, Front, One is leaking	
Boom Lift Cylinder(s)	★★★★☆	
Telescopic Boom Cylinders	★★★★☆	
Carriage Tilt Cylinder	★★★★☆	

Frame Leveling Cylinders	☆☆☆☆	
Steering Cylinders	☆☆☆☆	
Limited Function Check	The hydraulic system was operational. Had some residue underneath the unit, but don't see any leaks	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		

Hydraulics #5		
Hydraulics #6		
Hydraulics #7		
Hydraulics #8		
Hydraulics #9		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Boom Condition	★★★★☆	
Left Side of Boom		
Right Side of Boom		
Chain / Tensioners	★★★★☆	
Rollers and Guides	★★★★☆	
Boom Wear Guides	★★★★☆	

Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		

Chassis #8		
------------	--	---

Telehandler*

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 370/75-28 Brand: Firestone Model: dura force Tread Depth: 25/32	

Left Rear Tire	Size: 400/75-28 Brand: Firestone Model: but's force Tread Depth: 15/32	
Right Rear Tire	Size: 400/75-28 Brand: Firestone Model: dura force Tread Depth: 17/32	
Right Front Tire	Size: 370/75.28 Brand: Firestone Model: dura force Tread Depth: 23/32	
Wheel Condition	Right front bent	
Loader Quick Coupler	★★★★☆ genie Coupler, Not operationally checked	
Load Back Rest	★★★★☆	
Forks	★★★★☆	

Telehandler* #1		
Telehandler* #2		
Telehandler* #3		
Telehandler* #4		
Telehandler* #5		
Telehandler* #6		
Telehandler* #7		

Telehandler* #8		
Telehandler* #9		
Telehandler* #10		
Telehandler* #11		
Telehandler* #12		
Telehandler* #13		
Telehandler* #14		

Telehandler* #15		
Telehandler* #16		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved