

Location: Boom and Bucket


**TRUCK AND EQUIPMENT CONSULTING LLC – MINI TRACK LOADER SKID STEER
CHECKLIST (REQUIRED)**

Date
(Y/M/D) 1/25/2023

Inspector
Initials B.B.

(Basic Information)	
(Manufacturer)	Toro
(Model Number)	Dingo TX1000 Widetrack / Model 22328
(Serial Number)	403070098
(Year of Manufacturing)	2018
(Hour Meter Reading)	654.3 Hrs
(Transmission/Drive)	Hydrostatic
(Engine Model)	TIER 4 Kubota D1305 I3 1.26L 25Hp Diesel
(Hydraulic System Capacity)	15.2 gal reservoir
(Hydraulic Relief)	3000 psi
(Undercarriage)	1 sprocket, 5 rollers+1 idler (per side)

- A (Near to Brand New or Excellent Condition)
 B (A little Wear and Good Condition)
 C (Fair Workable Condition for Hour Meter Reading)
 D (Workable but minor repair is required)
 E (Workable but major repair is required)

Specification and Dimensions	
Serial Plate/Frame Inscription	403070098
Cabin+Canopy (Circle)	Stand On (no ROPS /FOPS)
Wheelbase	41 in
Tipping Load	3071 lbs
Drive Speed	4.7 mph
Fluid Capacities	Eng Oil =6.0 qt / Fuel =11.5 gal
Load Capacity	1075 lbs
Dump Height	81 in pin height / Max Op Ht =105 in
Operating Weight	2790 lbs
Track Width	127.6 in x 5.9 in
Attachments	Forks, 

		(Check List)					(Remarks)
		A	B	C	D	E	
GENERAL APPEARANCE	(General Appearance-Front)		X				Good appearance front components,panels+panel gaps,no wear issues
	(General Appearance-Rear)		X				Good appearance rear components,panels+panel gaps,no wear issues
	(General Appearance-Right)		X				Good appearance right components,panels+panel gaps,no wear issues
	(General Appearance-Left)		X				Good appearance left components,panels+panel gaps,no wear issues
	(General Appearance-Upper)		X				Upper surface panels+engine covers+panels Good appearance
	(Major / Minor Surface Rust)		X				No rust issues No rust cosmetics
	(Body Panel Rust Damage / Cancer)		X				No panel damages No dents No dings No rust
	(Visible Weld Repairs / Stress Cracks)		X				No patches or panels damages seen
	(Glass / Polycarbonate ? Condition ?)						N/A
	(Chassis / Undercarriage Damage)		X				Good appearance underside panels Dry appearance
OPERATOR'S STATION	(Operator Station)		X				Clean and straight Solid floors,Good panels, Good joysticks
	(Operator Controls and Switches)		X				Good appearance Operator controls Complete and working
	(Hour Meter Activity)		X				Working
	(Other Gauge Activity)		X				Working
	(Canopy Latches)						Engine cover panel+latches Good working condition
	(Safety - Horn / First Aid Kit)		X				Working
	(Operator Seat Condition)						N/A
(Safety - Seat Belts / Fire Extinguisher)						N/A	
E N G I N E	(Oil Color / Fluid Appearance / Particulates or Granuales)		X				Clean + Dry Good appearance No blow by seen at operating temps
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		X				Easy start Smooth Idle No unusual noise at startup or shut down
	(Engine Exhaust Color - White / Blue / Black / Clear)		X				Clear Clear at operating temp
	(Oil Leaks)		X				No active oil leaks seen from engine
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		X				No smoke issues at start up or when hot
	(Coolant Color / Fluid Appearance)		X				Good appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		X				No noises from cooling system
	(Coolant Leaks from Radiator)		X				No radiator leaks seen Good appearance of fins
	(Overall Engine Appearance Clean / Wet / Dry)		X				Clean and Dry appearance
	(Other)						
HYDRAULICS OVERALL	(Overall appearance of Hydraulic lines/fittings - worn/cracked)		X				Good appearance No dried seepages No fraying Dry+clean fittings
	(Hydraulic Pump Sounds / Noises)		X				Smooth No unusual pump noises or vibrations
	Wet or Damp hydraulic lines and fittings / fluid leaks)		X				No active leaks No dried seepages Pistons no discoloration no pitting
	(External Controls / Levers Condition)		X				Working
	(Hydraulics Service Records / Maintenance History)		X	X			Filters Marked 9/29/21 NSD @ 630 Hrs

ELECTRICAL	(Lighting System Condition)								N/A	
	(Reverse Alarm / Backup Signal)								N/A	
	(Battery Condition)		X						Battery compartment Dirty, battery + posts look good	
B R A K E S	(Other Electric Device Condition)		X						No diagnostic codes No service codes	
	(Foot Brake)		X						Good function No squeaks No unusual noises	
	(Inching Brake Functional & Working Condition)		X						Good function	
	(Parking Brake)		X						Good function	
	(Other Remarks)									
TRANSMISSION	(Clutch Noise / Function)		X						Smooth Shifting No unusual noises	
	(Transmission Noise / Function)		X						Good Forward and Reverse Function	
	(Shift Lever Condition & Function)		X						Shifter Good Appearance	
	(Other Remarks)									
HYDRAULICS CYLINDERS	(Lift)	(Oil Leak from Cylinder)		X					No active leaks seen	
		(Mounting Pin Condition)		X					Good appearance No wear issues	
	(Bucket)	(Oil Leak from Cylinder)		X					No active leaks seen	
		(Mounting Pin Condition)		X					Good appearance No wear issues	
	(Steering)	(Oil Leak from Cylinder)		X					No active leaks seen	
		(Mounting Pin Condition)		X					Good appearance No wear issues	
(Other Remarks)								Good appearance No wear issues		
C H A S S I S & COMPONENT	(Transom / Boom / Arm Function / Noise)		X						Quiet Lift + Drop No unusual noises Smooth function	
	(Slack in Pins / Loose Pins / Soft Bushings)		X						No vibration or noise	
	(Level stance and alignment)		X						Level Stance	
	(Right Track Roller/Idler Appearance)		X						Good appearance No wear issues	
	(Left Track Roller/Idler Appearance)		X						Good appearance No wear issues	
	(Track Side Guards Appearance)		X						Good appearance No wear issues	
	TRACKS	(Right)	Right Upper Appearance		X					Good appearance No wear issues
			Right Lower Appearance		X					Good appearance No wear issues
		(Left)	Left Upper Appearance		X					Good appearance No wear issues
			Left Lower Appearance		X					Good appearance No wear issues
	(Tracks Overall Condition)		X						Tracks =B- No cracks or tears seen Some surface wear only	
Attachment	(Overall Appearance)		X						Straight edge Good appearance No damage some minor surface scratches	
	(Bucket Edge)		X						Good appearance	
	(Bucket Articulation)		X						Good articulation of hydraulics	
	(Bucket Performance Vibrations ? Noises ?)		X						No unusual noises Smooth and Quiet Performance No vibrations	

OVERALL EXTERIOR RATING: B QUALITY: B
 OVERALL INTERIOR RATING: B SAFETY: B
 OVERALL PERFORMANCE: B FUNCTIONALITY: B
OVERALL EVALUATION GRADE: B
 FLUID ANALYSIS RECOMMENDED (Y/N) n OIL n COOLANT n

TRANSPORT DIMENSIONS:

Length: 100.7 in (w/std bkt)
 Width: 41 in
 Height: 53.2 in
 Weight: 2790 lbs

*A:Remaining Ratio 90% or more
 *B:Remaining Ratio 70% or more
 *C:Remaining Ratio 50% or more
 *D:Remaining Ratio 20% or more
 *E:Remaining Ratio 20% or less