Location:	Boom and	Bucket	

TRUCK AND EQUIPMENT CONSULTING LLC - SERVICE LUBE TRUCK

Date (Y/M/D	4/19/2023
Inspector Initials	A.L.

(Basic Information)				
(Make)	Ford			
(Model)	F550 SD XL Reg Cab 4x2 Dualie Rear			
(Serial Number)	1FDUF5HTXFEA34191			
(Year of Manufacturing/Origin)	2015 (built 4/2014)			
(Color)	White / Gray			
(Mileage)	159,022 Miles			
(Engine)	PowerStroke 6.7L 390Hp V8 Turbo Diesel			
(Transmission)	Automatic 6 Spd			
(No. of Tanks)	(4)=/ Used / Diesel /Hyd Oil / Motor Oil			

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

	Specifica	tion and Dimensions	
GVWR		19,500 lbs	
Hoses+Reels	(6) Diesel/	LubeOil/Grease Gun/Motor Oil/Hydraulic/Air Hose	
DOT		N/A	
Brake	Hydraulic		
Front / Rear Axle		Front =6500 lbs / Rear =14,706 lbs	
Tires		Sumitomo 225/70R 19.5	
Pump		Fill-Rite 12V 15 gal per min	
Rear		4.88	
Body		Diamond Plate Bed w/lock storage 2 Right/2 Left	
Other	s/n 1NAR10068859	Ingersol Rand Compressor Model 2475	
Other	Speed Aire System	Kohler Command Pro 429cc Engine	
		Overhead Safety Beacon, Side Steps, Thermaguard	
		Tank Gauges, Rear Work Lights, Digital Fill Meters	

	(Check List)	Α	В	С	D	Е	(Remarks)
GENERAL	(General Appearance-Front)		Χ				Good appearance of grille, bumpers, front fenders good panels No damage
APPEARANCE	(General Appearance-Rear)		Χ				Good appearance rear dump body Minor surface paint cosmetics
	(General Appearance-Right)		Χ				Right side panels+gaps Good appearance No damage
	(General Appearance-Left)		Χ				Left side panels+gaps Good appearance No damage Tank panels straight
	(General Appearance-Upper)			Χ			Areas of rust around fill necks on tanks, paint peel, panel stains No damage
	(Major / Minor Surface Rust)		Χ				No rust issues or rust damage Surface paint cosmetics only
	(Body Panels / Covers - Rust Damage / Cancer)		Χ				No rust cancer Minor paint cosmetics No damage
	(Visible Weld Repairs / Stress Cracks)		Χ				None seen
	(Glass Condition)		Χ				Good Glass
	(Chassis / Undercarriage Damage)		Χ				Good appearance Frame rails, underside components Dry appearance
	(Operator Cabin)			Χ			Dirty+Soiled headliner,floors,doors,steering wheel Normal wear+tear
OPERATOR'S	(Operator Controls and Switches)		Χ				Complete No broken switches or controls
COCKPIT	(Odometer Activity)		Χ				Working
	(Other Gauge Activity)		Χ	Χ			Gauges+display Working OIL CHANGE REQUIRED MESSAGE
	(Door / Canopy Latches)		Χ				Good Hood + Door latch function
	(Safety - Horn / First Aid Kit)		Χ				Horn Working
	(Operator Seat Condition)		Χ				Seats Good condition
	(Other)		Χ	Χ			OIL CHANGE REQUIRED MESSAGE ON DISPLAY
ENGINE	(Oil Color / Fluid Appearance)		Χ				Dirty Appearance No Blow-By at operating temp
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		Χ				Easy start No unusual noises Smooth Idle
	(Engine Exhaust Color - White / Blue / Black / Clear)		Χ				Clear / Clear at Temperature
	(Oil Leaks)		Χ				No dampness or wet areas Dry appearance
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		Χ				No smoke issues
	(Coolant Color / Fluid Appearance)		Χ				Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		Χ				No pump noises No coolant leaks seen
	(Coolant Leaks from Radiator)		Χ				None seen
	(Overall Engine Appearance Clean / Wet / Dry)		Х				Dirty but Dry appearance No rust No dried seepages seen

	I/O A A A A A A A A A A A A A A A A A A A			
	(Lighting System Condition)	Х		Working
	(Reverse Alarm / Backup Signal)	Χ		Working
ELECTRICAL	(Battery Condition)	Χ		Good appearance battery + battery terminals
	(Other Electric Device Condition)			
	FRONT TRACTOR TIRES	Χ		Tires =B Good appearance No side wall damage Inner Hubs Dry =B no rust
TIRES	TRAILER TIRES X4	Χ		Tires =B Good appearance Inner Hubs =B dry no rust
	OTHER	Χ		Tires + Hubs overall Good appearance
	(Clutch Noise / Function)	Χ		No unusual transmission noises or vibrations
TRANSMISSION	(Transmission Noise / Function)	Χ		Good Transmission function Forward and Reverse
	(Shift Lever Condition & Function)	Х		Good Shifter function
	(Other Remarks)	Х		Pedals Good appearance No damage from wear or tear
DIFFERENTIAL	(Rear Diff - Noises ?)	Χ		No Rear Diff Noises heard Dry appearance
BRAKES	(Foot Brake)	Χ		Good Brake Function
	(AIR BRAKE)			N/A
	(Parking Brake)	Χ		Good function
TANKS	(Tank Appearacne) Dried Seepages ? Leaks ?	Χ	Χ	No dents or dings No dried seepages Some panel stains No damage seen
HOSES	(Hoses+Reels Appearance)	Χ	Χ	Good appearance Fittings +Valves surface cosmetics No damage seen
COMPRESSOR	(Hose Leaks ? Fittings ?)			No damage seen Good appearance NOT PRESSURE TESTED
	(Compressor)			NOT TESTED
OPERATION	FORWARD & REVERSE	Χ		Good Forward and Reverse function
	STEERING + BRAKES	Χ		Good Steering and Brakes function
	ENGINE	Χ		Engine Smooth Idle Good Response
	CONTROLS	Χ		Driver Controls + Switches Good Function and Response
RATINGS	OVERALL VISUAL INSPECTION	Χ	Χ	Good body panels,panel gaps Some panel stains+surface rust on fill necks
	COMMENTS	Χ	Χ	Above Average Normal wear+tear for usage Tanks Not Pressure Tested
	OVERALL PERFORMANCE INSPECTION	Χ		Good travel performance Good steering+brakes Good engine response
	COMMENTS	Χ	Χ	Oil Change Required Message, Good engine+transmission performance

FLUID SAMPLE REQUEST (Y/N) <u>n</u> OIL n COOLANT <u>n</u>
OVERALL CONDITION GRADE: C+
OVERALL PERFORMANCE: <u>B</u> FUNCTIONALITY: <u>B</u>
OVERALL INTERIOR RATING: <u>C+</u> SAFETY: <u>B</u>
OVERALL EXTERIOR RATING: <u>C+</u> QUALITY: <u>C/C+</u>

TIRES *A:Remaining Ratio 90% or more *B:Remaining Ratio 70% or more *C:Remaining Ratio 50% or more *D:Remaining Ratio 20% or more *E:Remaining Ratio

20% or less