



## Inspection Report (On-Highway Dump Truck)

### General Info

Year	2015
Make	Ford
Model	F750
Serial Number	3frn7fafv706758
Truck Odometer Reading	47025.5
Current Inspection / State Cert / DOT	Arizona
Previous Application (e.g., earth moving, mining, demolition, etc)	Road construction

### Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	20ft
Width (ft and inches)	8ft
Height (ft and inches)	9ft
Wheelbase (ft and inches)	12ft
GVWR (lbs)	25999

### Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Drive Type	4X2
Overdrive	No
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Dump truck
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No

### Exterior 360 Walkaround

### Exterior 360 Walkaround

## Inspection Report (On-Highway Dump Truck)

<p><b>Instructions</b></p>	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"><li>- Front</li><li>- 45 degree corner shot of left front</li><li>- 45 degree corner shot of right front</li><li>- Left side</li><li>- Right side</li><li>- Rear</li><li>- 45 degree corner shot of left rear</li><li>- 45 degree corner shot of right rear</li></ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"><li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li></ul>
<p><b>Exterior Walkaround Photos</b></p>	

Inspection Report (On-Highway Dump Truck)





### Inspection Report (On-Highway Dump Truck)



### General Appearance Inspection Points

#### General Appearance

## Inspection Report (On-Highway Dump Truck)

<p>Close-up Exterior Photos</p>	
<p>Body Panels</p>	<p>2 - Above Average Wear</p>
<p>Body Panel Condition</p>	<p>Visible chipped paint or dents</p>
<p>Body Panels Photos</p>	

Inspection Report (On-Highway Dump Truck)



**Inspection Report (On-Highway Dump Truck)**


Doors / Canopy Latches	4 - Like New, Recently Replaced
Steps / Ladders	4 - Like New, Recently Replaced
Handrails	0





### Inspection Report (On-Highway Dump Truck)

Cab Interior Photos




### Inspection Report (On-Highway Dump Truck)



Odometer Activity	4 - Like New, Recently Replaced
Controls/Switches/Gauges	4 - Like New, Recently Replaced
Brake System Type	Hydraulic



## Inspection Report (On-Highway Dump Truck)

Clutch	4 - Like New, Recently Replaced
Clutch Function	Clutch is functioning as expected
Horn	4 - Like New, Recently Replaced
Horn Condition	Horn is functioning as expected
Reverse Alarm / Backup Camera	4 - Like New, Recently Replaced
Reverse Alarm / Backup Camera Condition	Reverse alarm working as expected
Heater & A/C	4 - Like New, Recently Replaced
Heat & A/C Condition	Heater and A/C work as expected
Interior Lights	4 - Like New, Recently Replaced
Interior Lights Condition	All interior lights are installed and functioning
Seats/Seat Belts	2 - Above Average Wear
Seats/Seat Belt Condition	Seat(s) have minor surface staining or small tears
Seats/ Seat Belt Photos	
Cab Interior Overall Rating	4 - Like New, Recently Replaced

## Engine Inspection Points

<b>Engine</b>	
Engine Type (Make, Model, Cylinders, Hp)	6.7 Cummins
Emissions Tier	Tier 4i

### Inspection Report (On-Highway Dump Truck)

Engine Fuel Type	Diesel
Engine Photos	
	

## Inspection Report (On-Highway Dump Truck)



Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	4 - Like New, Recently Replaced
Radiator	4 - Like New, Recently Replaced
Belts	4 - Like New, Recently Replaced
Hoses	4 - Like New, Recently Replaced
Water Pump	4 - Like New, Recently Replaced
Cooling System Leaks	No
Oil Leaks	No
Oil Color / Appearance	4 - Like New, Recently Replaced
Fuel Leaks	No
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	4 - Like New, Recently Replaced
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants

## Inspection Report (On-Highway Dump Truck)

Overall Engine Appearance	Clean & dry
---------------------------	-------------

### Chassis & Drivetrain Inspection Points

#### On-Highway: Undercarriage Components

#### Chassis Inspection Points


Chassis Inspection Points	Take photos of all undercarriage and chassis components including frame, suspension, axles, steering, and brake components. Note any damage or wear.
---------------------------	--

Chassis & Undercarriage Photos	
--------------------------------	---

Inspection Report (On-Highway Dump Truck)




### Inspection Report (On-Highway Dump Truck)

		
<b>Frame</b>	4 - Like New, Recently Replaced	
<b>Comments</b>	Clean, no patches	
<b>Suspension</b>	4 - Like New, Recently Replaced	
<b>Steer Axle Condition</b>	4 - Like New, Recently Replaced	
<b>Steering Components</b>	4 - Like New, Recently Replaced	





## Inspection Report (On-Highway Dump Truck)

<b>Steering Component Photos</b>	
<b>Overall Chassis Condition</b>	4 - Like New, Recently Replaced


### Drivetrain Inspection Points

<b>Transmission Info (Make/Model)</b>	6speed manual
<b>Transmission</b>	4 - Like New, Recently Replaced
<b>Transmission Condition</b>	No unusual noises or vibrations


## Inspection Report (On-Highway Dump Truck)

<p>Transmission Condition Photos</p>	
<p>PTO</p>	<p>2 - Above Average Wear</p>
<p>Comments</p>	<p>Wet/ leaking</p>
<p>PTO Photos</p>	
<p>Differential</p>	<p>Check condition of the differential(s). Take photos and notes as relevant.</p>

## Inspection Report (On-Highway Dump Truck)

<b>Rear Differential</b>	4 - Like New, Recently Replaced
<b>Rear Differential Condition</b>	Dry housing appearance, no unusual noises heard during operation
<b>Rear Differential Photos</b>	
<b>Front Differential</b>	0
<b>Brake Shoe Thickness</b>	70%
<b>Air Brake System Leaks</b>	N/A
<b>Air Brake Hose Condition</b>	4 - Like New, Recently Replaced

## Inspection Report (On-Highway Dump Truck)

<b>Air Brake System Photos</b>	
<b>Overall Drivetrain Condition</b>	4 - Like New, Recently Replaced

### Additional Undercarriage Components

<b>Equipped with DPF (Diesel Particulate Filter)</b>	Yes
<b>DPF Condition</b>	4 - Like New, Recently Replaced

### Wheels & Tires Inspection Points

#### Wheels & Tires

### Wheels & Tires Inspection Points

<b>Wheels &amp; Hub Condition</b>	4
-----------------------------------	---

## Inspection Report (On-Highway Dump Truck)

Wheels & Hub Photos





### Inspection Report (On-Highway Dump Truck)





Wheel Seal Leaks	No
Tire Brand	Sumiton
Tire Size	148/145k 11r22.5

## Inspection Report (On-Highway Dump Truck)

<b>Front Left Tire - Ratio Remaining</b>	70%
<b>Front Left Tire Photos</b>	
<b>Front Right Tire - Ratio Remaining</b>	70%
<b>Front Right Tire Photos</b>	
<b>Rear Right Tire - Ratio Remaining</b>	70%

### Inspection Report (On-Highway Dump Truck)


<p>Rear Right Tire Photos</p>	
<p>Rear Left Tire - Ratio Remaining</p>	<p>70%</p>
<p>Rear Left Tire Photos</p>	
<p>Additional Axles</p>	<p>Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.</p>



## Inspection Report (On-Highway Dump Truck)

### Addition Axle Inspection

#### Additional Axle

<b>Instructions</b>	Check the condition of additional axle(s), wheels & tires. Note any damage or wear. Take photos.
<b>Steerable?</b>	No
<b>Drop Axle?</b>	No
<b>Super Dump?</b>	No
<b>Axle Condition</b>	4 - Like New, Recently Replaced
<b>Comments</b>	No signs. Of dents or leaking
<b>Axle Condition Photos</b>	
<b>Wheels &amp; Tires</b>	0

### Additional Inspection Points

#### On Highway - Dump Truck

#### Additional Inspection Points: Dump Body, Tailgate, Support & Tarp

<b>Dump Body Make &amp; Material</b>	Steel
<b>Dump Body Length (ft and inches)</b>	8ft
<b>Dump Body Height (ft and inches)</b>	3ft
<b>Bed Body</b>	3 - Normal Wear & Tear
<b>Comments</b>	Dents/scratches

### Inspection Report (On-Highway Dump Truck)

Bed Body Photos





Inspection Report (On-Highway Dump Truck)





Tailgate

3 - Normal Wear & Tear

## Inspection Report (On-Highway Dump Truck)

<p>Tailgate Photos</p>	
<p>Tailgate Latch</p>	<p>4 - Like New, Recently Replaced</p>
<p>Tailgate Latch Photos</p>	

**Inspection Report (On-Highway Dump Truck)**

	
<p><b>Support Frame</b></p>	<p>4 - Like New, Recently Replaced</p>
<p><b>Support Frame Photos</b></p>	
<p><b>Tarp</b></p>	<p>4 - Like New, Recently Replaced</p>

## Inspection Report (On-Highway Dump Truck)

### Additional Inspection Points: Dump Hydraulics

Hydraulics	Check the condition of the hydraulics. Check lines, hoses, fittings, leaks, function, etc. Note any damage or wear. Take photos.
------------	--

### Functional Test

Forward & Reverse	4 - Operating Within Factory Spec
Steering	4 - Operating Within Factory Spec
Brakes	4 - Operating Within Factory Spec
Engine	4 - Operating Within Factory Spec
Controls	4 - Operating Within Factory Spec
Overall Functional Test Comments	Other then cosmetics it functions great
Operating Video	<a href="#">Click to Download</a>

### Inspection Summary

#### Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	4 - Like New, Recently Replaced
Safety Rating	4 - Like New, Recently Replaced
Quality Rating	4 - Like New, Recently Replaced
Functionality Rating	4 - Operating Within Factory Spec
Overall Rating	4 - Like New, Recently Replaced
What's Great About the Machine	Clean and low miles
What Needs Work	Paint on bed
Date/Time	05-24-2023