



Inspection Report (Forklift)

General Info

B&B Stock Number	A7574493
Year	2012
Make	Raymond
Model	425-C40TT
Serial Number	425-12-34885
Serial Plate Photo	
Hour Meter Reading	9239

Inspection Report (Forklift)

Hour Meter Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Warehouse

Dimensions

A. Length (ft and inches)	6ft 0In
B. Width (ft and inches)	3ft 5in
C. Height (ft and inches)	7ft 4In
Operational Weight (lbs)	9734 lbs

Features and Configuration

Max Lift Height	20ft 11in
Max Lift Capacity	4000lbs
Forks / Work Tool Specs	Class 2 Carriage and forks. 42 inch forks
Side Shift	Yes
Tilt Carriage	Yes
Tilt Mast	Yes
Frame Leveling	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Tire Type	Solid, Non-marking
Heat	No



Inspection Report (Forklift)

A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No
Charger Included	No
Other Configuration Details / Notes	Charger is NOT included in the sale.

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video


Embedded Photo					
Exterior Walkaround Photos					
Operating Video	Click to Download				
Additional Video	Click to Download				
Additional Video	Click to Download				

General Appearance Inspection Points


























General Appearance

Inspection Report (Forklift)

General Appearance Photos



Inspection Report (Forklift)

This is the battery(engine). Comes with a water cord attachment for appropriate operation of the battery.

General Appearance Inspection Points


Inspection Report (Forklift)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	4 - Very Light or Minimal Wear	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	-1	
Glass	-1	
Mirrors	-1	
Exterior Lights	5 - Like New, Recently Replaced	
Overall Exterior	4 - Very Light or Minimal Wear	
Comments	Many scratches on the machines body panel on each side. Nothing deeper than those scratches. Exterior in good shape with minimal west outside scratches.	

Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos					
Control Station Type	Open Cab (OROPS), Canopy				
Control Type	Pilot Controls				
Control Configuration	N/A				
Comments	No wear and tear at all at the control station				
Seat	-1				
Cabin Lights	3 - Normal Wear & Tear				
Safety Lock Out / Stop	3 - Normal Wear & Tear				

Inspection Report (Forklift)

Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	Switches have good functionality, minor cosmetic damage observed
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional, with some minor wear and/or cosmetic damage
Other Gauge Activity	-1
Heater & A/C	-1
Travel Alarm	0
Horn	5 - Like New, Recently Replaced
Backup Camera	0
Control Station Overall Rating	5 - Like New, Recently Replaced

Section 1








Electric Engine and Operating System

Electric Engine and Operating System Photos

Engine Plate Photo



Inspection Report (Forklift)

Electric Engine and Operating System Photos					
	<p>The battery(engine) with the brake(for the left wheel) on top of it</p>			<p>The right brake and battery.</p>	
					
		<p>Water cord attachment for battery operation</p>			
Operating Voltage	36				
Battery Condition	3 - Normal Wear & Tear				
Comments	Battery was replaced in June of 2022				
Battery Charger	1 - Service Required				
Comments	Charger is NOT Included				
Cables & Connections	3 - Normal Wear & Tear				
Tight Connections?	Yes				
Solenoids	3 - Normal Wear & Tear				
Wire Harness	3 - Normal Wear & Tear				
Cooling System	3 - Normal Wear & Tear				
Fuse Panel(s)	3 - Normal Wear & Tear				
Computer Appearance	-1				
Electric Motor	3 - Normal Wear & Tear				
Screen Discoloration?	N/A				
Electric Operating System Overall Rating	3 - Normal Wear & Tear				
Overall Engine Appearance	Clean & Dry				


Inspection Report (Forklift)

Overall Electric Operating System Comments	Brakes have no rust. Engine compartment is dry with little dust. No visible wear and tear
--	---

Drivetrain Inspection Points


Drivetrain

Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	No
Drive Type	Other (see comments)
Other Drive Type	unable to determine
Transmission Components	-1
Parking Brake	3 - Normal Wear & Tear
Parking Brake Function	Good brake function
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Very light wear and tire, if any.
Front Axle	0
Rear Axle	0

Wheels & Tires


Wheels & Tires Inspection Points

Wheel Type	Solid, Non-Marking
Wheel Seal Leaks	No
Tire Brand	Raymond OEM
Tire Size	6.25x7x11 In
Front Left Tire - Ratio Remaining	70%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	70%













Inspection Report (Forklift)

Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	90%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	90%
Wheels & Hubs	4 - Very Light or Minimal Wear
Comments	The front tires are 80% remaining. Option not available to fill in.

Chassis Inspection Points

Chassis Photos	
----------------	--






Inspection Report (Forklift)

	    
	    
	 
Frame	3 - Normal Wear & Tear
Stance	-1
Carriage Appearance	3 - Normal Wear & Tear
Mast Condition	3 - Normal Wear & Tear
Chain / Tensioners	4 - Very Light or Minimal Wear
Rollers & Guides	3 - Normal Wear & Tear
Overall Chassis	4 - Very Light or Minimal Wear
Overall Chassis Comments	Clear use of the chassis, but we've taken care of with no obvious drop off with care, no sounds evident in use or application








Hydraulics Overall Inspection Points

Hydraulics Overall


Hydraulic System Inspection Points

Hydraulic System Photos	    
--------------------------------	--

Inspection Report (Forklift)

	    
	 
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	Very clean hydraulic system

Additional Attachments

Additional Attachment(s)

Additional Attachments

Attachment Type	Sliding pallet for side to side fork use
Attachment Condition	3 - Normal Wear & Tear
Comments	No additional attachments

Inspection Report (Forklift)

Attachment Photos		
-------------------	---	--

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Engine compartment has very minimal wear, dry and and no dust. Hydraulics and chains are in very good condition and well cleaned and/or lubricated. The machine functions with no kinks or odd sounds

Overall Assessment

Overall Assessment

Inspection Rating Criteria	<table border="1"> <thead> <tr> <th>Rating Scale</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>1 - Service Required</td> <td>Requires immediate repairs to function as expected.</td> </tr> <tr> <td>2 - Above Average Wear & Tear</td> <td>Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.</td> </tr> <tr> <td>3 - Normal Wear & Tear</td> <td>Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.</td> </tr> <tr> <td>4 - Very Light or Minimal Wear</td> <td>Exhibits very minimal wear. Operation is better than expected given age and usage.</td> </tr> <tr> <td>5 - Like New, Recently Replaced</td> <td>Excellent condition, free of visible wear or damage. Operation is within factory specifications.</td> </tr> </tbody> </table>	Rating Scale	Explanation	1 - Service Required	Requires immediate repairs to function as expected.	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Rating Scale	Explanation													
1 - Service Required	Requires immediate repairs to function as expected.													
2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.													
3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.													
4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.													
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.													
Exterior Rating	5 - Like New, Recently Replaced													
Interior Rating	4 - Very Light or Minimal Wear													
Safety Rating	5 - Like New, Recently Replaced													
Quality Rating	5 - Like New, Recently Replaced													
Functionality Rating	5 - Like New, Recently Replaced													



Inspection Report (Forklift)

Overall Rating	4 - Very Light or Minimal Wear
What's Great About the Machine	The inside of the machine is well taken care of with no obvious wear. The front panel fans provide extra care for the driver, also the light on the top of the frame of the forklift provides extra safety. The hydraulics are notably well taken care of.
What Needs Work	The machine body panel cosmetics can be improved.
Date/Time	03-12-2024
Inspector Name	Jayshun Clark