


Inspection Report (Forklift)

General Info

B&B Stock Number	A6866866
Year	2007
Make	Toyota
Model	7BRU18
Serial Number	7BRU18-34370
Serial Plate Photo	
Hour Meter Reading	3010

Inspection Report (Forklift)

Hour Meter Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Warehouse

Dimensions

A. Length (ft and inches)	5ft 11in
B. Width (ft and inches)	3ft 3in
C. Height (ft and inches)	7ft 11in
Operational Weight (lbs)	2300 lbs

Features and Configuration

Max Lift Height	17ft 6in
Max Lift Capacity	3500pbs
Forks / Work Tool Specs	Class 2 Carriage and forks. 42inch long forks
Side Shift	Yes
Tilt Carriage	Yes
Tilt Mast	Yes
Frame Leveling	No
Additional Attachment(s)?	Yes
Auxiliary Hydraulics	Yes
Tire Type	Solid, Non-marking
Heat	No

Inspection Report (Forklift)

A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Charger Included	No
Other Configuration Details / Notes	Charger NOT included. For the Charger you will need an additional charging station, but it comes with the cables that apply to the charging station(attached to the machine). There are no exact spec modifications included in the manual. Only directions/instructions for operating the equipment.

OMM Specifications



OMM Specifications

Detail Specifications	Take photos of the detailed spec pages included in the operator's manual
-----------------------	--

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Embedded Photo					
Exterior Walkaround Photos					
Operating Video	Click to Download				


Inspection Report (Forklift)

Additional Video	Click to Download
Additional Video	Click to Download


General Appearance Inspection Points

General Appearance


General Appearance Photos



Inspection Report (Forklift)



Inspection Report (Forklift)



General Appearance Inspection Points

Inspection Report (Forklift)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Other (see comments)	
Comments	Partially torn step where foot lies	
Handrails	0	
Glass	3 - Normal Wear & Tear	
Glass Condition	Other (see comments)	
Comments	No crack or chip observes. It needs a simple wash	
Mirrors	0	
Exterior Lights	3 - Normal Wear & Tear	
Overall Exterior	4 - Very Light or Minimal Wear	
Comments	Machine showing light wear from general use considering age. It is mostly clean with some minimal rust at the chassis and behind the forks(side shifter). The load back rest has some minor rust.	


Control Station Inspection Points

Control Station

Control Station Photos



Inspection Report (Forklift)


	
Control Station Type	Open Cab (OROPS)
Control Type	Pilot Controls
Control Configuration	N/A
Seat	-1
Cabin Lights	-1
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	Switches have good functionality, minor cosmetic damage observed, All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional, with some minor wear and/or cosmetic damage
Other Gauge Activity	-1
Heater & A/C	-1
Travel Alarm	-1
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling, Good cabin appearance, solid floors, panels, and ceiling
Comments	Overall control station clear of dirt, clutter. Minimal signs of wear

Section 1

Electric Engine and Operating System

Electric Engine and Operating System Photos

Inspection Report (Forklift)

Engine Plate Photo	
Operating Voltage	36
Battery Condition	4 - Very Light or Minimal Wear
Comments	Battery was replaced in March of 2023
Battery Charger	1 - Service Required
Comments	Charger is NOT included.
Cables & Connections	3 - Normal Wear & Tear
Tight Connections?	Yes
Solenoids	3 - Normal Wear & Tear
Wire Harness	3 - Normal Wear & Tear
Cooling System	-1
Fuse Panel(s)	5 - Like New, Recently Replaced
Computer Appearance	-1
Electric Motor	5 - Like New, Recently Replaced
Screen Discoloration?	N/A
Electric Operating System Overall Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Clean & Dry
















Inspection Report (Forklift)

Overall Electric Operating System Comments	The fuse panel is located inside of the machine under the control panel. Also the electric engine system pictures are located in the drivetrain section. They are both in the same place Charger is NOT included in the sale.
---	--

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points







Drivetrain Photos					
					
					
Hydrostatic Transmission?	No				
Transmission Info (Make/Model/Speeds)	Toyota OEM				
Drive Type	2WD				
Transmission Components	0				
Parking Brake	3 - Normal Wear & Tear				
Parking Brake Function	Good brake function				
Overall Drivetrain Rating	3 - Normal Wear & Tear				
Overall Drivetrain Comments	Minimal wear and tear. There is some minor rust on the brake, which is located on top of the drive motor.				
Front Axle	0				

Inspection Report (Forklift)

Rear Axle	0
-----------	---

Wheels & Tires




















Wheels & Tires Inspection Points

Wheel Type	Solid, Non-Marking		
Wheel Seal Leaks	No		
Tire Brand	Toyota OEM Standard Polyurethane		
Tire Size	13in diameter		
Front Left Tire - Ratio Remaining	N/A		
Front Right Tire - Ratio Remaining	N/A		
Rear Right Tire - Ratio Remaining	90%		
Rear Right Tire Photos			
Rear Left Tire - Ratio Remaining	90%		
Rear Left Tire Photos			
Wheels & Hubs	4 - Very Light or Minimal Wear		

Chassis Inspection Points

Chassis Photos					
					

Inspection Report (Forklift)


					
	Some dirt and small wear				Some wear near lunnrication
					
	Minor wear				
					
					
Frame	3 - Normal Wear & Tear				
Stance	3 - Normal Wear & Tear				
Carriage Appearance	3 - Normal Wear & Tear				
Mast Condition	4 - Very Light or Minimal Wear				
Chain / Tensioners	3 - Normal Wear & Tear				
Rollers & Guides	4 - Very Light or Minimal Wear				
Overall Chassis	4 - Very Light or Minimal Wear				
Overall Chassis Comments	The rollers are in good condition with no wear or rust. Mast in great shape. Chain also with no rust and finely lubricated. The carriage has some minor wear where lubrication was applied.				

Hydraulics Overall Inspection Points


Hydraulics Overall

Hydraulic System Inspection Points

Inspection Report (Forklift)

Hydraulic System Photos	
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

Hydraulic Cylinder Inspection Points


Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	Maintained well. No rust, wear or grime. Clean

Additional Attachments

Additional Attachment(s)

Additional Attachments

Inspection Report (Forklift)

Attachment Type	Sideshifter
Attachment Make	Toyota
Attachment Size / Specs	N/A
Attachment Condition	4 - Very Light or Minimal Wear
Attachment Photos	

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	4 - Very Light or Minimal Wear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Machine is in good condition overall with little wear and tear, only being some paint chips and rust on the brakes and small places.

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	4 - Very Light or Minimal Wear	

Inspection Report (Forklift)

Interior Rating	4 - Very Light or Minimal Wear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal Wear & Tear
Overall Rating	3 - Normal Wear & Tear
Summary Video	Click to Download
What's Great About the Machine	The machine is electric, and fine tuned, lubricated, with some minor chips and dirt. Otherwise the functionality is good and no kinks in the machine or it's behaviors. Operates exactly as you'd expect it to.
What Needs Work	The brakes could be replaced.
Any Additional Info from the Seller?	Charger is NOT included in the sale. Battery was replaced in March of 2023
Date/Time	03-12-2024
Inspector Name	Jayshun Clark