

## 2007 GENIE Z-60 / 0

Specifications	
Year	2007
Make	Genie
Model	Z-60
Date of Inspection	03/27/2024
Location of Inspection	5702 Honey Grove Rd, Ely, IA, 52227
Serial Number	Z6007-8031
Engine Hours	981
EMS Warning Lights	No Active Warnings
Travel Control	N/A
Operator's Seat	N/A
Mirrors	N/A
Radio	N/A
A/C	N/A
Steering Wheel	N/A
Pedals	No Damages Observed
Floorboard	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Switches and Controls	See Notes
Steps	N/A
Handrails	No Damages Observed
Oil Dipstick	Good Color/Good Level
Engine Compartment	See Notes
Exhaust	No Damages Observed
Axles	No Damages Observed
ROPS	No Damages Observed
Front Lights	N/A
Rear Lights	N/A
Front Left Tire Condition	See Notes
Front Left Tire Brand	Blackstone-OTR
Front Left Tire Size	15-19.5
Rear Left Tire Condition	See Notes
Rear Left Tire Brand	Blackstone-OTR
Rear Left Tire Size	15-19.5
Front Right Tire Condition	See Notes
Front Right Tire Brand	Blackstone-OTR
Front Right Tire Size	15-19.5
Rear Right Tire Condition	See Notes
Rear Right Tire Brand	Blackstone-OTR
Rear Right Tire Size	15-19.5
Attachments - Basket	No Damages Observed

### Equipment Photo



### Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/q9iwB7w2QPX6RxnM>

### Notes / Description

The unit runs and drives. The decal is peeling off the control panel on the unit. The compartment door by the control panel on the unit has cracks in it. There appears to be a battery charger in the engine compartment that is attached to the battery, and an extension cord is hooked to the charger. The rubber boot is missing from the bottom of the air filter housing. The bolts for the battery cable ends are rusty. The front right tire has a cut in the tread lug. The tires appear to be a little low on air pressure. The horn did not sound in the video. The travel or operation alarms were not operational during the video. The exhaust sound indicates there may be a leak in it during the video. The right side compartment door may have some paint damage on the upper part.

# Aspen Field Services



Front Left / 03-27-2024



Front / 03-27-2024

# Aspen Field Services



Front Right / 03-27-2024



Right / 03-27-2024

# Aspen Field Services



Rear Right / 03-27-2024



Rear / 03-27-2024

# Aspen Field Services




Rear Left / 03-27-2024



Left / 03-27-2024

# Aspen Field Services



Serial Number: Z6007-8031 / 03-28-2024



Switches and Controls / 03-27-2024

# Aspen Field Services



EMS Warning Lights / 03-27-2024



Switches and Controls / 03-27-2024

# Aspen Field Services



Engine Hours / 03-27-2024



Engine Compartment / 03-27-2024



# Aspen Field Services



Engine Compartment / 03-27-2024



Engine Compartment / 03-27-2024

# Aspen Field Services



Battery Compartment / 03-27-2024



Oil Dipstick / 03-27-2024

# Aspen Field Services



Engine Compartment / 03-27-2024



Basket / Attachments / ROPS / Handrails / 03-27-2024

# Aspen Field Services



Basket / Attachments / ROPS / Handrails / 03-27-2024



Basket / Attachments / ROPS / Handrails / 03-27-2024

# Aspen Field Services



Basket / Attachments / ROPS / Handrails / 03-27-2024



Pedals / 03-27-2024

# Aspen Field Services



Basket / Attachments / ROPS / Handrails / 03-27-2024



Axle / 03-27-2024

# Aspen Field Services



Axle / 03-27-2024



Axle / 03-27-2024

# Aspen Field Services



Axle / 03-27-2024



Rear Left Tire Condition / 03-27-2024



# Aspen Field Services



Rear Left Tire Condition / 03-27-2024



Rear Left Tire Brand / 03-27-2024

# Aspen Field Services



Rear Left Tire Size / 03-27-2024



Front Left Tire Condition / 03-27-2024

# Aspen Field Services



Front Left Tire Brand / 03-27-2024



Front Left Tire Size / 03-27-2024

# Aspen Field Services



Front Left Tire Condition / 03-27-2024



Front Right Tire Brand / 03-27-2024

# Aspen Field Services



Front Right Tire Size / 03-27-2024



Front Right Tire Condition / 03-27-2024

# Aspen Field Services



Front Right Tire Condition / 03-27-2024



Rear Right Tire Brand / 03-27-2024

# Aspen Field Services



Rear Right Tire Size / 03-27-2024



Rear Right Tire Condition / 03-27-2024

# Aspen Field Services



Rear Right Tire Condition / 03-27-2024