





Inspection Report (Skid Steer/Track Loader)

General Info

B&B Stock Number	A9516995
Year	2019
Make	John Deere
Model	330G
Serial Number	1T0330GMKKF351812
Serial Plate Photo	 <p>The serial plate photo shows a yellow metal plate with a black label. The label contains the text: 'JOHN DEERE', 'Product Identification Number', '1T0330GMKKF351812', 'SKIDSTEER 330G', and 'MADE IN USA DEERE & COMPANY, MOLINE, ILLINOIS, USA'. Above the label, there are three phone numbers: (208) 888-3337, (208) 324-2900, and (208) 634-3903, along with their respective locations: Las Vegas, NV and Elko, NV. To the right of the label, there is a red and white sign that says 'Call 432' and 'AN'.</p>
Hour Meter Reading	433.5
Hour Meter Photo	 <p>The hour meter photo shows a close-up of the instrument cluster. The digital display shows '433.4' and a small icon of a truck. To the right of the display is a needle gauge with a green arc and a red tip. The John Deere logo is visible at the top of the instrument panel.</p>
Previous Application (e.g., earth moving, mining, demolition, etc)	Earth moving

Inspection Report (Skid Steer/Track Loader)

Location / GPS	
	

Features and Configuration

Travel System	Wheel & Tires
Bucket	Yes
Additional Attachment(s)?	Yes
Auxiliary Hydraulics	Yes
High Flow	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	Yes

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	
	

Inspection Report (Skid Steer/Track Loader)

Operating Video	Click to Download
-----------------	-----------------------------------

General Appearance Inspection Points

General Appearance

General Appearance Photos



General Appearance Inspection Points


Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	0	
Steps / Ladders	3 - Normal Wear & Tear	
Handrails	3 - Normal Wear & Tear	
Glass	3 - Normal Wear & Tear	
Mirrors	3 - Normal Wear & Tear	
Exterior Lights	3 - Normal Wear & Tear	
Overall Exterior	3 - Normal Wear & Tear	
Comments	Normal wear and tear no major issues to report	

Inspection Report (Skid Steer/Track Loader)

Control Station Inspection Points

Control Station

Control Station Photos




Control Station Photos	
Control Station Type	Open Cab (OROPS)
Control Type	Pilot Controls
Control Configuration	Configurable (SAE and ISO)
Seat	3 - Normal Wear & Tear
Cabin Lights	3 - Normal Wear & Tear
Safety Lock Out / Stop	3 - Normal Wear & Tear
Controls & Switches	3 - Normal Wear & Tear
Hour Meter Activity	3 - Normal Wear & Tear
Other Gauge Activity	3 - Normal Wear & Tear
Heater & A/C	0
Travel Alarm	0
Horn	3 - Normal Wear & Tear
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear

Engine Inspection Points

Engine

Engine Compartment Photos

Inspection Report (Skid Steer/Track Loader)

Engine Data Plate	
Engine Compartment Photos	
	
Engine Type (Make, Model, Cylinders, Hp)	Unable to verify
Emissions Tier	Tier 4F
Engine Serial Number	Unable to very
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Radiator	3 - Normal Wear & Tear
Belts	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Water Pump	3 - Normal Wear & Tear
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No


Inspection Report (Skid Steer/Track Loader)

Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	Normal wear and tear no major issues to report

Drivetrain Inspection Points

Drivetrain


Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	Yes
Speeds	Variable Speed
Drive Type	AWD
Transmission Components	0
Drive Motors	3 - Normal Wear & Tear
Parking Brake	0
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report







Travel System Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

Wheel Type	Pneumatic
Wheel Seal Leaks	No
Tire Brand	Galaxy
Tire Size	14x17.5
Front Left Tire - Ratio Remaining	70%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	70%

Inspection Report (Skid Steer/Track Loader)

Front Right Tire Photos	 
Rear Right Tire - Ratio Remaining	70%
Rear Right Tire Photos	 
Rear Left Tire - Ratio Remaining	70%
Rear Left Tire Photos	 
Wheels & Hubs	3 - Normal Wear & Tear

Chassis Photos

Chassis Photos	    
	    
	    
	    

Chassis Inspection Points













Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Lift Arms	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	2 - Above Average Wear & Tear
Comments	Ripped wires
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear no major issues to report

Inspection Report (Skid Steer/Track Loader)









Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos	    
	    
	 
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	    
	  
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear

Bucket Inspection Points

Bucket Photos	    
---------------	--

Inspection Report (Skid Steer/Track Loader)

	  
Bucket	2 - Above Average Wear & Tear
Comments	Bent side wall and mounting area
Bucket Edge / Deflectors	2 - Above Average Wear & Tear
Comments	Blade worn

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear no major issues to report

Overall Assessment

Overall Assessment

Inspection Rating Criteria	<table border="1"> <thead> <tr> <th>Rating Scale</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>1 - Service Required</td> <td>Requires immediate repairs to function as expected.</td> </tr> <tr> <td>2 - Above Average Wear & Tear</td> <td>Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.</td> </tr> <tr> <td>3 - Normal Wear & Tear</td> <td>Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.</td> </tr> <tr> <td>4 - Very Light or Minimal Wear</td> <td>Exhibits very minimal wear. Operation is better than expected given age and usage.</td> </tr> <tr> <td>5 - Like New, Recently Replaced</td> <td>Excellent condition, free of visible wear or damage. Operation is within factory specifications.</td> </tr> </tbody> </table>	Rating Scale	Explanation	1 - Service Required	Requires immediate repairs to function as expected.	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
	Rating Scale	Explanation											
	1 - Service Required	Requires immediate repairs to function as expected.											
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.											
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.											
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.											
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.												
Exterior Rating	3 - Normal Wear & Tear												
Interior Rating	3 - Normal Wear & Tear												
Safety Rating	3 - Normal Wear & Tear												
Quality Rating	3 - Normal Wear & Tear												



Inspection Report (Skid Steer/Track Loader)

Functionality Rating	3 - Normal Wear & Tear
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	The thing that's great about this machine is that it starts right up with no abnormal Noises heard
What Needs Work	The things that need work on this machine are the wiring to the bucket release, The damage to the rear grille And damage to the rear right panel.
Date/Time	05-16-2024
Inspector Name	Javier Bocanegra