



Inspection Report (Excavator)

General Info

B&B Stock Number	A6164397
Year	2015
Make	John Deere
Model	35G
Serial Number	1FF035GXLFK274629
Serial Plate Photo	
Hour Meter Reading	2304
Hour Meter Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Earth moving

Features and Configuration

Travel System	Rubber Track Undercarriage
Bucket	Yes
Bucket Specs	12" rock bucket
Blade	Yes
Additional Attachment(s)	No
Hydraulic Coupler	No
Auxiliary Hydraulics	Yes

Inspection Report (Excavator)

Hydraulic Thumb	No
Heat	No
A/C	No
Radio	No
Backup Camera	No
Grade Control System	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior Walkaround Photos

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos					
					

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos					
					
					
					

General Appearance Inspection Points





Inspection Report (Excavator)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear & Tear	
Doors / Canopy Latches	0	
Steps / Ladders	3 - Normal Wear & Tear	
Handrails	3 - Normal Wear & Tear	
Glass	0	
Mirrors	0	
Exterior Lights	3 - Normal Wear & Tear	
Overall Exterior	2 - Above Average Wear & Tear	
Comments	Above average wear and tear due to dents and areas of surface rust observed	

Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos					
					
					
					
Control Station Type	Open Cab (OROPS)				
Control Type	Pilot Controls				
Control Configuration	Configurable (SAE and ISO)				
Seat	2 - Above Average Wear & Tear				

















Inspection Report (Excavator)

Seat Condition	Seat(s) have minor surface staining or small tears, Seat belt secures properly
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Controls & Switches	3 - Normal Wear & Tear
Hour Meter Activity	2 - Above Average Wear & Tear
Hour Meter Condition	Hour meter is functional, with some minor wear and/or cosmetic damage
Other Gauge Activity	2 - Above Average Wear & Tear
Other Gauge Condition	Gauges are functional, with some wear and/or cosmetic damage
Heater & A/C	0
Travel Alarm	0
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear




Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					
					
					

Inspection Report (Excavator)





	  	
Engine Type (Make, Model, Cylinders, Hp)	Yanmar	
Emissions Tier	Undetermined	
Engine Serial Number	09004	
Engine Fuel Type	Diesel	
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Exhaust Color	Clear	
Battery	3 - Normal Wear & Tear	
Radiator	3 - Normal Wear & Tear	
Belts	3 - Normal Wear & Tear	
Hoses	3 - Normal Wear & Tear	
Water Pump	3 - Normal Wear & Tear	
Cooling System Leaks	No	
Coolant Appearance	3 - Normal Wear & Tear	
Oil Leaks	No	
Oil Appearance	3 - Normal Wear & Tear	
Fuel Leaks	No	
Equipped with DPF (Diesel Particulate Filter)	No	
Requires DEF (Diesel Exhaust Fluid)	No	
Overall Engine Rating	3 - Normal Wear & Tear	
Overall Engine Appearance	Dusty & dry	
Overall Engine Comments	Normal wear and tear	

Drivetrain Inspection Points









































Drivetrain

Drivetrain Inspection Points

Inspection Report (Excavator)

Drivetrain Photos	   	
Hydrostatic Transmission?	Yes	
Speeds	Variable Speed	
Drive Type	N/A (Track Undercarriage)	
Transmission Components	0	
Drive Motors	3 - Normal Wear & Tear	
Parking Brake	0	
Overall Drivetrain Rating	3 - Normal Wear & Tear	
Overall Drivetrain Comments	Normal wear and tear	

Chassis Inspection Points

Chassis Photos	    	
	    	
	    	
	    	
	    	
	    	
	    	
	    	
































Inspection Report (Excavator)

Boom Condition	3 - Normal Wear & Tear
Stick Condition	3 - Normal Wear & Tear
Boom Base Pin & Bushings	3 - Normal Wear & Tear
Boom to Stick Pin & Bushings	3 - Normal Wear & Tear
Stick to Bucket Pin & Bushings	3 - Normal Wear & Tear
Turntable Bearing	3 - Normal Wear & Tear
Bottom Covers	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear no major issues to report

Travel System Inspection Points

Rubber Track Undercarriage

Undercarriage Photos

Undercarriage Photos					
					
					
					
					
					
					

Inspection Points

Track Width (inches)	12"
----------------------	-----




Inspection Report (Excavator)

Track Length (inches)	72"
Roller Frames	3 - Normal Wear & Tear
Track Belt	1 - Service Required
Comments	Cuts and gouges in track
Rubber Belt Drive Lugs	2 - Above Average Wear & Tear
Track Tensioners	3 - Normal Wear & Tear
Front Idlers	3 - Normal Wear & Tear
Rear Idlers	0
Track Rollers	3 - Normal Wear & Tear
Sprockets	3 - Normal Wear & Tear
Overall Undercarriage Rating	3 - Normal Wear & Tear
Left Track Belt - Percent Remaining Estimate	30%
Right Track Belt - Percent Remaining Estimate	30%
Overall Comments	Above average wear and tear to both track

Hydraulics Overall Inspection Points
















Hydraulics Overall

Hydraulic System Inspection Points






Hydraulic System Photos					
					
					
Wet or Damp Hydraulic Lines / Fittings	No				
Hydraulic Lines/Fittings	3 - Normal Wear & Tear				
Hydraulic Pump(s)	3 - Normal Wear & Tear				
Unusual Noises	No				

Hydraulic Cylinder Inspection Points

Inspection Report (Excavator)

Hydraulic Cylinder Photos	    
	    
	    
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	Normal wear and tear no major issues to report





Bucket Inspection Points

Attachment Photos	    
Bucket	3 - Normal Wear & Tear
Bucket Teeth	3 - Normal Wear & Tear
Blade	0
Blade Edge	0

Additional Attachment Inspection Points

Additional Attachment(s)

Additional Attachments

Attachment Type	Tooth bucket
Attachment Make	Tag
Attachment Size / Specs	24"
Attachment Condition	3 - Normal Wear & Tear
Attachment Photos	   

Functional Test

Functionality Assessment

Functionality Assessment

Inspection Report (Excavator)

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear no major issues to report

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	2 - Above Average Wear & Tear	
Interior Rating	2 - Above Average Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
What's Great About the Machine	The great thing about this machine is that it starts right up with no abnormal noises heard	
What Needs Work	The things that need work on this machine are both tracks with cuts and gouges, dents on exterior of machine and the dim LCD display due to sun exposure	
Date/Time	05-16-2024	
Inspector Name	Javier Bocanegra	