




Inspection Report (Skid Steer/Track Loader)

General Info

B&B Stock Number	A9471539
Year	2022
Make	Bobcat
Model	T64
Serial Number	B4SD13783
Serial Plate Photo	
Hour Meter Reading	305.1
Hour Meter Photo	

Inspection Report (Skid Steer/Track Loader)

Location / GPS	
Lat: 27.6134117308743 Long: -80.38897072482771	

Features and Configuration

Travel System	Track Undercarriage
Bucket	Yes
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
High Flow	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	Yes
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos					
					












Inspection Report (Skid Steer/Track Loader)

					
					
Operating Video	Click to Download				

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos					
					
					

General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	4 - Very Light or Minimal Wear	
Doors / Canopy Latches	4 - Very Light or Minimal Wear	
Steps / Ladders	4 - Very Light or Minimal Wear	
Handrails	4 - Very Light or Minimal Wear	
Glass	4 - Very Light or Minimal Wear	
Mirrors	4 - Very Light or Minimal Wear	
Exterior Lights	4 - Very Light or Minimal Wear	
Overall Exterior	4 - Very Light or Minimal Wear	


Inspection Report (Skid Steer/Track Loader)

Comments	Machine is pretty new, was used on one job, has been serviced and maintained since purchase.
----------	--

Control Station Inspection Points

Control Station


Control Station Photos

Control Station Photos	
Control Station Type	Open Cab (OROPS)
Control Type	Pilot Controls
Seat	3 - Normal Wear & Tear
Cabin Lights	4 - Very Light or Minimal Wear
Safety Lock Out / Stop	4 - Very Light or Minimal Wear
Controls & Switches	4 - Very Light or Minimal Wear
Hour Meter Activity	4 - Very Light or Minimal Wear
Other Gauge Activity	4 - Very Light or Minimal Wear
Heater & A/C	0
Travel Alarm	4 - Very Light or Minimal Wear
Horn	4 - Very Light or Minimal Wear
Backup Camera	4 - Very Light or Minimal Wear
Control Station Overall Rating	4 - Very Light or Minimal Wear

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos	
Drive Type	N/A (Track Undercarriage)
Transmission Components	4 - Very Light or Minimal Wear
Parking Brake	4 - Very Light or Minimal Wear
Overall Drivetrain Rating	4 - Very Light or Minimal Wear
Overall Drivetrain Comments	Tracks look good from my POV

Chassis Photos

Inspection Report (Skid Steer/Track Loader)

Chassis Photos		
----------------	---	---







Chassis Inspection Points

Frame	4 - Very Light or Minimal Wear
Stance	4 - Very Light or Minimal Wear
Lift Arms	4 - Very Light or Minimal Wear
Chassis to Arm Pins	4 - Very Light or Minimal Wear
Quick Coupler	4 - Very Light or Minimal Wear
Quick Coupler to Arms Pins	4 - Very Light or Minimal Wear
Overall Chassis	4 - Very Light or Minimal Wear
Overall Chassis Comments	Don't have any extra thoughts on Chassis

Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos					
					
Wet or Damp Hydraulic Lines / Fittings	No				
Hydraulic Lines/Fittings	4 - Very Light or Minimal Wear				
Hydraulic Pump(s)	4 - Very Light or Minimal Wear				
Unusual Noises	No				

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos					
					
Mounting Pins	4 - Very Light or Minimal Wear				
Cylinder Oil Leaks	No				

Inspection Report (Skid Steer/Track Loader)

Hydraulic System Overall	4 - Very Light or Minimal Wear
--------------------------	--------------------------------

Functional Test

Functionality Assessment

Functionality Assessment

Engine	4 - Very Light or Minimal Wear
Transmission/Drivetrain	4 - Very Light or Minimal Wear
Travel (Forward/Reverse/Steering)	4 - Very Light or Minimal Wear
Brakes	4 - Very Light or Minimal Wear
Hydraulic System	4 - Very Light or Minimal Wear
Electric Operating System	4 - Very Light or Minimal Wear
Controls	5 - Like New, Recently Replaced
Safety Systems	4 - Very Light or Minimal Wear
Core Functions	4 - Very Light or Minimal Wear
Attachments	4 - Very Light or Minimal Wear
Overall Functional Test Comments	See Video

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	4 - Very Light or Minimal Wear	
Interior Rating	4 - Very Light or Minimal Wear	
Safety Rating	4 - Very Light or Minimal Wear	
Quality Rating	4 - Very Light or Minimal Wear	
Functionality Rating	4 - Very Light or Minimal Wear	
Overall Rating	4 - Very Light or Minimal Wear	
What's Great About the Machine	Fairly new, used on one job.	
What Needs Work	Nothing to my knowledge	
Date/Time	05-13-2024	



Inspection Report (Skid Steer/Track Loader)

Inspector Name	Ja'Min Brown
----------------	--------------