


Seller Onboarded Machine v2.0

General Info

B&B Stock Number	A5239334
Category	Excavator
Year	2007
Make	Caterpillar
Model	308C
Serial Number / VIN	CAT0308CPCPE03771
Serial Number Plate / VIN Sticker	
	06-25-2024 02:59 PM
Hour Meter or Odometer Reading	4446

Seller Onboarded Machine v2.0



Dimensions

Overall Length (ft and inches)	19ft 2in
Overall Width (ft and inches)	7ft 7in
Overall Height (ft and inches)	8ft 7in
Operational Weight (lbs)	17100

Off Highway Equipment

Travel System	Track Undercarriage
Fuel Type	Diesel
Control Station Type	Enclosed Cab (EROPS)

Seller Onboarded Machine v2.0

Operator Controls	Pilot Controls
Seat Type	Fixed
A/C	N/A
Heat	Yes
Radio	N/A
Reverse Camera	N/A
All of the above are fully functional	N/A

Excavator

Blade	No
Bucket	Yes
Bucket Size (yd3 / inches)	28in
Auxiliary Hydraulics	Yes
Thumb	No
Extended Stick Option	No
Quick Coupler	No
Grade Control	N/A

Vacuum Trucks

Tank Size (Gallons)	1
Boom Reach (ft)	Na
Suction Hose Diameter	Na
Suction Hose Length	Na
Inlet Diameter	Na
Outlet Diameter	Na
Water Spray System	N/A
Hand Held Control	N/A
Vibration	N/A

360 Walkaround Photos

Seller Onboarded Machine v2.0

Exterior Walkaround Photos




General Appearance


Close-Up Exterior Photos



Seller Onboarded Machine v2.0



Control Station



Control Station Overall Comments	A/c needs work.
----------------------------------	-----------------

Engine

Seller Onboarded Machine v2.0




Engine Data Plate










Engine Compartment



Seller Onboarded Machine v2.0

			
Engine Type (Make, Model, Cylinders, Hp)	Mitsubishi, 4M40-EA, 4 cylinder, 55hp		
Engine Overall Comments	Engine turns on immediately, no weird noise, no white smoke, no leak.		

Drivetrain Components








Drivetrain Photos			
			
			
Drivetrain Comments	Clean, no apparent issue		

Underbody Inspection Points

Underbody Photos		
-------------------------	---	--

Hydraulics













Seller Onboarded Machine v2.0

<p>Hydraulic Pump/Fittings/Hoses/Cylinders/Pins</p>			
			
			
<p>Hydraulic System Comments</p>	<p>Pump is clean and dry. Working properly.</p>		

Chassis

<p>Chassis Photos</p>			
-----------------------	---	--	---

Seller Onboarded Machine v2.0

			
			
			
			
<p>Comments</p>	<p>Machine frame is in good shape. No apparent issue.</p>		

Attachments

Seller Onboarded Machine v2.0

Attachment Photos			
Attachment Comments	Machine comes with 1 bucket, no blade		

Functionality Assessment

Is this machine fully operable?	Yes
Video - Operational or 360	Click to Download
What's great about this machine	Quick machine, aux read for a thumb, hammer. Cabin is clean
What needs work	A/c needs work