



Inspection Report (Skid Steer/Track Loader)

General Info

B&B Stock Number	A6259258
Year	2023
Make	ASV
Model	RT-75
Serial Number	ASVRT075EPDS04896
Serial Plate Photo	 <p>A photograph of a silver metal serial plate for an ASV machine. The plate contains the following information: ASV logo, 840 Lily Lane Grand Rapids, MN 55744, MODEL RT75, MODEL YEAR 2023, and PIN ASVRT075EPDS04896. A yellow warning sign with a black arrow and a tree icon is partially visible below the plate.</p>
Hour Meter Reading	218
Hour Meter Photo	 <p>A photograph of a Danfoss digital hour meter. The display shows a reading of 218.2 hours. Other information on the display includes 4(4), 071724, 11:13 am, and a 'Signal Not Available' message. The Danfoss logo is visible above the display.</p>
Previous Application (e.g., earth moving, mining, demolition, etc)	General Rental

Dimensions

Inspection Report (Skid Steer/Track Loader)

A. Length (ft and inches)	12' 8"
B. Width (ft and inches)	5' 10"
C. Height (ft and inches)	7'


Features and Configuration

Travel System	Track Undercarriage
Bucket	Yes
Bucket Specs	72"
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
High Flow	No
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	Yes

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	
Operating Video	Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos	
--------------------------	--

Inspection Report (Skid Steer/Track Loader)



General Appearance Inspection Points



Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	4 - Very Light or Minimal Wear	
Body Panel Condition	No visible damage, good paint condition and panel fitment	
Doors / Canopy Latches	4 - Very Light or Minimal Wear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	4 - Very Light or Minimal Wear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	4 - Very Light or Minimal Wear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	4 - Very Light or Minimal Wear	
Glass Condition	Glass intact, no visible damage	
Mirrors	4 - Very Light or Minimal Wear	
Mirror Condition	Mirrors present and intact, no visible damage	
Exterior Lights	4 - Very Light or Minimal Wear	
Exterior Lights Condition	No visible damage, lighting system is operational	
Overall Exterior	4 - Very Light or Minimal Wear	
Comments	Minor cosmetic wear and tear	

Control Station Inspection Points

Control Station

Control Station Photos

Inspection Report (Skid Steer/Track Loader)




Control Station Photos	
	
Control Station Type	Open Cab (OROPS)
Control Type	Pilot Controls
Control Configuration	ISO (JD)
Seat	4 - Very Light or Minimal Wear
Seat Condition	Seat(s) in good condition, no stains or tears in upholstery
Cabin Lights	4 - Very Light or Minimal Wear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Safety Lock Out / Stop	4 - Very Light or Minimal Wear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	4 - Very Light or Minimal Wear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	4 - Very Light or Minimal Wear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	4 - Very Light or Minimal Wear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	4 - Very Light or Minimal Wear
Horn	4 - Very Light or Minimal Wear
Backup Camera	0
Control Station Overall Rating	4 - Very Light or Minimal Wear
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling

Engine Inspection Points

Engine

Engine Compartment Photos

Inspection Report (Skid Steer/Track Loader)

Engine Data Plate	
Engine Compartment Photos	
	
Engine Type (Make, Model, Cylinders, Hp)	Cummins
Emissions Tier	Tier 4F
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	N/A
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	4 - Very Light or Minimal Wear
Radiator	4 - Very Light or Minimal Wear
Belts	4 - Very Light or Minimal Wear
Hoses	4 - Very Light or Minimal Wear
Water Pump	0
Cooling System Leaks	No
Oil Leaks	No
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No


Inspection Report (Skid Steer/Track Loader)

Overall Engine Rating	4 - Very Light or Minimal Wear
Overall Engine Appearance	Clean & dry
Overall Engine Comments	No visible or audible issues.

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	Yes
Speeds	Variable Speed
Drive Type	N/A (Track Undercarriage)
Parking Brake	4 - Very Light or Minimal Wear
Overall Drivetrain Rating	4 - Very Light or Minimal Wear
Overall Drivetrain Comments	No visible issues

Travel System Inspection Points

Rubber Track Undercarriage

Undercarriage Photos

Undercarriage Photos	
----------------------	--

Inspection Points

Track Width (inches)	18
Roller Frames	4 - Very Light or Minimal Wear
Track Belt	4 - Very Light or Minimal Wear
Rubber Belt Drive Lugs	4 - Very Light or Minimal Wear
Track Tensioners	4 - Very Light or Minimal Wear
Front Idlers	4 - Very Light or Minimal Wear
Rear Idlers	4 - Very Light or Minimal Wear
Track Rollers	4 - Very Light or Minimal Wear
Sprockets	4 - Very Light or Minimal Wear

Inspection Report (Skid Steer/Track Loader)

Overall Undercarriage Rating	4 - Very Light or Minimal Wear
Left Track Belt - Percent Remaining Estimate	N/A
Right Track Belt - Percent Remaining Estimate	N/A
Overall Comments	No visible issues with undercarriage

Chassis Photos

Chassis Photos	    
----------------	--





Chassis Inspection Points

Frame	4 - Very Light or Minimal Wear
Stance	4 - Very Light or Minimal Wear
Lift Arms	4 - Very Light or Minimal Wear
Chassis to Arm Pins	4 - Very Light or Minimal Wear
Quick Coupler	4 - Very Light or Minimal Wear
Quick Coupler to Arms Pins	4 - Very Light or Minimal Wear
Overall Chassis	4 - Very Light or Minimal Wear
Overall Chassis Comments	No visible issues





Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos	   
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	4 - Very Light or Minimal Wear
Hydraulic Pump(s)	4 - Very Light or Minimal Wear
Unusual Noises	No

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	   
Mounting Pins	4 - Very Light or Minimal Wear
Cylinder Oil Leaks	No

Inspection Report (Skid Steer/Track Loader)

Hydraulic System Overall	4 - Very Light or Minimal Wear
--------------------------	--------------------------------

Bucket Inspection Points

Bucket Photos	
Bucket	4 - Very Light or Minimal Wear
Bucket Edge / Deflectors	4 - Very Light or Minimal Wear

Functional Test

Functionality Assessment

Functionality Assessment

Engine	4 - Very Light or Minimal Wear
Transmission/Drivetrain	4 - Very Light or Minimal Wear
Travel (Forward/Reverse/Steering)	4 - Very Light or Minimal Wear
Brakes	0
Hydraulic System	4 - Very Light or Minimal Wear
Electric Operating System	4 - Very Light or Minimal Wear
Controls	4 - Very Light or Minimal Wear
Safety Systems	4 - Very Light or Minimal Wear
Core Functions	4 - Very Light or Minimal Wear
Attachments	4 - Very Light or Minimal Wear
Overall Functional Test Comments	Ready for the jobsite

Overall Assessment

Overall Assessment

Inspection Rating Criteria	<table border="1"> <thead> <tr> <th>Rating Scale</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>1 - Service Required</td> <td>Requires immediate repairs to function as expected.</td> </tr> <tr> <td>2 - Above Average Wear & Tear</td> <td>Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.</td> </tr> <tr> <td>3 - Normal Wear & Tear</td> <td>Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.</td> </tr> <tr> <td>4 - Very Light or Minimal Wear</td> <td>Exhibits very minimal wear. Operation is better than expected given age and usage.</td> </tr> <tr> <td>5 - Like New, Recently Replaced</td> <td>Excellent condition, free of visible wear or damage. Operation is within factory specifications.</td> </tr> </tbody> </table>	Rating Scale	Explanation	1 - Service Required	Requires immediate repairs to function as expected.	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
	Rating Scale	Explanation											
	1 - Service Required	Requires immediate repairs to function as expected.											
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.											
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.											
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.											
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.												
Exterior Rating	4 - Very Light or Minimal Wear												
Interior Rating	4 - Very Light or Minimal Wear												
Safety Rating	4 - Very Light or Minimal Wear												
Quality Rating	4 - Very Light or Minimal Wear												



Inspection Report (Skid Steer/Track Loader)

Functionality Rating	4 - Very Light or Minimal Wear
Overall Rating	4 - Very Light or Minimal Wear
What's Great About the Machine	Unique undercarriage - smooth ride
What Needs Work	N/A
Date/Time	07-17-2024
Inspector Name	Rex Walz