



## Inspection Report (Bulldozer)

### General Info

B&B Stock Number	A1104116
Year	1984
Make	Caterpillar
Model	834B
Serial Number	92Z0194
Serial Plate Photo	
Hour Meter Reading	860 - meter replaced in April 2019, hours before unknown.
Hour Meter Photo	

### Dimensions

A. Length (ft and inches)	28.66
---------------------------	-------

## Inspection Report (Bulldozer)

B. Width (ft and inches)	11.67
C. Height (ft and inches)	13.46


























### Features and Configuration

Blade	Yes
Blade Type	S
Ripper	No
Heat	Yes
A/C	Yes
Radio	No
Backup Camera	No
Grade Control System	No
Telematics	No
Other Configuration Details / Notes	Hour meter was installed in April of 2019 and reflects hours since then. Unable to confirm hours prior to 2019.
OMM (Operator & Maintenance Manual)	No


### Exterior Walkaround Photos

#### 360 Walkaround & Operating Video





















#### Walkaround Photos & Operating Video

Exterior Walkaround Photos					
					
					
					
					

Inspection Report (Bulldozer)




























## Inspection Report (Bulldozer)

					
					
					
					
Operating Video	<a href="#">Click to Download</a>				

## General Appearance Inspection Points

### General Appearance

### General Appearance Photos

Close-up Exterior Photos					
					
					
					
					

## General Appearance Inspection Points


## Inspection Report (Bulldozer)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents, Areas of surface rust observed, Areas of rust corrosion or rust cancer observed	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	3 - Normal Wear & Tear	
Glass Condition	Glass is broken or shattered, Other (see comments)	
Mirrors	3 - Normal Wear & Tear	
Mirror Condition	Mirrors present and intact, no visible damage	
Exterior Lights	3 - Normal Wear & Tear	
Exterior Lights Condition	No visible damage, lighting system is operational	
Overall Exterior	3 - Normal Wear & Tear	
Comments	Rear Glass broken	

## Control Station Inspection Points

### Control Station

### Control Station Photos

Control Station Photos	
Control Station Type	Enclosed Cab (EROPS)
Control Type	Lever Controls
Control Configuration	Unable to confirm
Seat	3 - Normal Wear & Tear
Cabin Lights	3 - Normal Wear & Tear



## Inspection Report (Bulldozer)

Safety Lock Out / Stop	3 - Normal Wear & Tear
Controls & Switches	3 - Normal Wear & Tear
Hour Meter Activity	3 - Normal Wear & Tear
Other Gauge Activity	0
Heater & A/C	2 - Above Average Wear & Tear
Heater & A/C Condition	Fan only, heating and A/C components inoperative
Travel Alarm	3 - Normal Wear & Tear
Horn	3 - Normal Wear & Tear
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear

## Engine Inspection Points

### Engine

### Engine Compartment Photos

<p>Engine Data Plate</p>	
<p>Engine Compartment Photos</p>	


## Inspection Report (Bulldozer)

Engine Type (Make, Model, Cylinders, Hp)	3408
Emissions Tier	Tier 0
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear at operating temperature
Battery	3 - Normal Wear & Tear
Radiator	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Water Pump	3 - Normal Wear & Tear
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Leaks	Yes
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components, Dusty & dry
Overall Engine Comments	Good

## Drivetrain Inspection Points

### Drivetrain


## Drivetrain Inspection Points

Drivetrain Photos	
Drive Type	AWD
Transmission Components	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear

## Inspection Report (Bulldozer)

Overall Drivetrain Comments	Good
-----------------------------	------


### Chassis Inspection Points

Chassis Photos	
Push Arm / C-Frame Condition	3 - Normal Wear & Tear
Push Arm Pivot / C-Frame Trunnions Condition	3 - Normal Wear & Tear
Tilt Linkage Pin & Bushings	3 - Normal Wear & Tear
Angle Linkage Pin & Bushings	3 - Normal Wear & Tear
Blade Trunnions / Bushings	3 - Normal Wear & Tear
Frame Condition	3 - Normal Wear & Tear
Belly Pans	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear


### Hydraulics Overall Inspection Points

#### Hydraulics Overall

#### Hydraulic System Inspection Points

Hydraulic System Photos	
Wet or Damp Hydraulic Lines / Fittings	Yes
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No

#### Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	Good

### Attachment Inspection Points

#### Attachments



## Inspection Report (Bulldozer)

### Additional Attachments

Attachment Type	Photos of blade in exterior sections.
Attachment Condition	0
Comments	Tow behind attachment in some pictures is NOT included in sale.

### Functional Test

#### Functionality Assessment

#### Functionality Assessment

Engine	0
Transmission/Drivetrain	0
Travel (Forward/Reverse/Steering)	0
Brakes	0
Hydraulic System	0
Electric Operating System	0
Controls	0
Safety Systems	0
Core Functions	0
Attachments	0
Overall Functional Test Comments	None

### Inspection Summary

#### Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	



## Inspection Report (Bulldozer)

What's Great About the Machine	Normal wear
What Needs Work	Regular maintenance
Any Additional Info from the Seller?	None
Date/Time	07-22-2024
Inspector Name	Terry Price