

General Info

B&B Stock Number	A6415625
Category	Service Truck
Year	2015
Make	Ford
Model	F250
Fleet ID	WC045
Serial Number / VIN	1FT7W2BTXFEB05270
Serial Number Plate / VIN Sticker	MED. BY FORD MOTOR CO FRACING GAVR: SATURE D7/4 SATURE STORATE L27/11R TTAS 500 kPg/75 PS/100 AT 500 kPg/000 THIS UPICE CONFORMS TO ALL APPLICATE DATA AN PS/000 THIS VEHICLE CONFORMS TO ALL APPLICATE DATA AN PS/000 THIS VEHICLE SATURE TS TANABASE MANUFACTURE SHOWN ADDR THE TO ALL
Hour Meter Reading	241009
Hour Meter Photo	E R N D M Z 1

Dimensions

Overall Length (ft and inches)	21' 3"
Overall Width (ft and inches)	6' 8"
Overall Height (ft and inches)	6' 7"
Wheel Base (ft and inches) - ON HIGHWAY MACHINES	14' 4"
Operational Weight (lbs)	



Off Highway Equipment

Travel System	
Comments	
Drive Type	
Comments	
Fuel Type	
Control Station Type	
Operator Controls	
A/C	
Heat	
Radio	
Reverse Camera	

All On-Highway Trucks

Is this vehicle titled?	No
Cab Type	Crew Cab
Drive Type	4X4
Comments	
Transmission	Automatic
Fuel Type	Diesel
PTO	No
Engine Brake	No
Air Brakes	No
A/C	Yes
Heat	Yes
Radio	Yes
Rear Camera	No
Cruise Control	Yes
Over Drive	Yes

Backhoe

Loader Bucket	
Loader Bucket Size (yd3 / inches)	
Digging Bucket	
Bucket Size (yd3 / inches)	
Extend-a-hoe	



Outriggers/Stabilizers	
Auxiliary Hydraulics	
Quick Coupler	

Bulldozer

Blade	
Blade Type	
Ripper	
GPS/Grade Control System	
System Make/Model	

Compact Track Loader

High Flow	
Loader Bucket	
Bucket Size (yd3 / inches)	
Auxiliary Hydraulics	
Quick Coupler	

Compactor

Blade	
Vibratory System	
Water Spray System	

Excavator

Blade	
Bucket	
Bucket Size (yd3 / inches)	
Auxiliary Hydraulics	
Thumb	
Thumb Type	
Extended Stick Option	
Stick Length (ft. in.)	
Quick Coupler	

Forklift

Forks	
Length x Width (inches)	
Side Shift	



Lifts

Jib	
Outriggers/Stabilizers	
Hydraulic Leveling	
Electrical Power to Platform	
Motor Grader	
Ripper	
Blade	
Push Block	
Front/Mid Scarifier	
GPS/Grade Control System	
System Make/Model	
Scraper	
Engine Configuration	
Elevating Bowl	
GPS/Grade Control System	
System Make/Model	
Skid Steer	
Loader Bucket	
Bucket Size (yd3 / inches)	
High Flow	
Auxiliary Hydraulics	
Quick Coupler	
Skip Loader	

Skip Loader

Loader Bucket	
Bucket Size (yd3 / inches)	
Box Blade	
Auxiliary Hydraulics	
Quick Coupler	

Telehandler

Forks	
Length x Width (inches)	
Work Basket	



Make/ Model

No

Crane

Outriggers/Stabilizers	
Hydraulic Leveling	
Side Shift	
Quick Coupler	
Wheel Loader	
Loader Bucket	
Bucket Size (yd3 / inches)	
Forks	
Length x Width (inches)	
Auxiliary Hydraulics	
Quick Coupler	
Generator	
Towable?	
Trailer VIN	
Trailer GVWR (Gross Vehicle Weight Rating)	
Is this trailer titled?	
Trailer Brakes	
kW Output / Power Rating (kW)	
Bucket Truck	
Lift Make/Model	
Lift SN Plate	
Date of Last Periodic / Annual Inspection	
Work Basket	
Outriggers / Stabilizers	
Service/Specialty Truck	
Auxiliary Engine	No
Auxiliary Fuel Tank	Yes
Lube System	No
Air Compressor	No
Make/ Model	
Welder	No



Make/ Model	
Hitch	No
Hitch Type	
Other Hitch Type	
Tank Trucks	
Tank Size (Gallons)	
Water Spray System	
Trailer	
Trailer GVWR (Gross Vehicle Weight Rating)	
Is this trailer titled?	
Trailer Brakes	
Hitch	
Other Hitch Type	

Other Features & Attachments

OMM (Operator & Maintenance Manual)	Yes
Other Features & Attachments	Rear tool box

360 Walkaround Photos



General Appearance





Exterior Comments	Rear left fender damage, both running boards damaged, driver wiper arm missing

Control Station

Control Station	
Control Station	
Control Station Overall Comments	A/C not blowing cold, ripped driver seat, dirty seats, check engine light on, tire pressure light on, brake pedal is spongy when applied



Engine

Engine Data Plate	
Engine Compartment	
Engine Type (Make, Model, Cylinders, Hp)	Ford
Engine Overall Comments	Dusty and dirty engine compartment, corrosion on battery posts, wasp infestation

Drivetrain Components



Drivetrain Comments

Hydraulics

Hydraulic Pump/Fittings/Hoses/Cylinders/Pin s	
Hydraulic System Comments	

Chassis

Chassis Photos	





Comments

Underbody Inspection Points

Underbody Photos



Underbody Comments

Attachments



Attachment Comments

Functionality Assessment

Is this machine operable?	Yes
Video - Operational or 360	Click to Download
Comments	Both runningboards damaged, Rear left fender damage, damage to tailgate, Check engine light on, tire pressure light on and spongy brakes when applied