



Direct To Auction Form

General Info

B&B Stock Number	A7426657
Category	Service Truck
Year	2016
Make	Ram
Model	4500
Fleet ID	34009
Serial Number / VIN	3C7WPLFL7GG360166
Serial Number Plate / VIN Sticker	
Hour Meter Reading	213188.7
Hour Meter Photo	

Dimensions

Overall Length (ft and inches)	24' 3"
Overall Width (ft and inches)	7' 10"
Overall Height (ft and inches)	7'11"
Wheel Base (ft and inches) - ON HIGHWAY MACHINES	16' 3"
Operational Weight (lbs)	



Direct To Auction Form

Off Highway Equipment

Travel System	
Comments	
Drive Type	
Comments	
Fuel Type	
Control Station Type	
Operator Controls	
A/C	
Heat	
Radio	
Reverse Camera	

All On-Highway Trucks

Is this vehicle titled?	Yes
Cab Type	Crew Cab
Drive Type	4X4
Comments	
Transmission	Automatic
Fuel Type	Diesel
PTO	No
Engine Brake	No
Air Brakes	No
A/C	Yes
Heat	Yes
Radio	Yes
Rear Camera	Yes
Cruise Control	Yes
Over Drive	Yes

Backhoe

Loader Bucket	
Loader Bucket Size (yd3 / inches)	
Digging Bucket	
Bucket Size (yd3 / inches)	
Extend-a-hoe	

Direct To Auction Form

Outriggers/Stabilizers	
Auxiliary Hydraulics	
Quick Coupler	

Bulldozer

Blade	
Blade Type	
Ripper	
GPS/Grade Control System	
System Make/Model	

Compact Track Loader

High Flow	
Loader Bucket	
Bucket Size (yd ³ / inches)	
Auxiliary Hydraulics	
Quick Coupler	

Compactor

Blade	
Vibratory System	
Water Spray System	

Excavator

Blade	
Bucket	
Bucket Size (yd ³ / inches)	
Auxiliary Hydraulics	
Thumb	
Thumb Type	
Extended Stick Option	
Stick Length (ft. in.)	
Quick Coupler	

Forklift

Forks	
Length x Width (inches)	
Side Shift	

Direct To Auction Form

Lifts

Jib	
Outriggers/Stabilizers	
Hydraulic Leveling	
Electrical Power to Platform	

Motor Grader

Ripper	
Blade	
Push Block	
Front/Mid Scarifier	
GPS/Grade Control System	
System Make/Model	

Scraper

Engine Configuration	
Elevating Bowl	
GPS/Grade Control System	
System Make/Model	

Skid Steer

Loader Bucket	
Bucket Size (yd3 / inches)	
High Flow	
Auxiliary Hydraulics	
Quick Coupler	

Skip Loader

Loader Bucket	
Bucket Size (yd3 / inches)	
Box Blade	
Auxiliary Hydraulics	
Quick Coupler	

Telehandler

Forks	
Length x Width (inches)	
Work Basket	

Direct To Auction Form

Outriggers/Stabilizers	
Hydraulic Leveling	
Side Shift	
Quick Coupler	

Wheel Loader

Loader Bucket	
Bucket Size (yd ³ / inches)	
Forks	
Length x Width (inches)	
Auxiliary Hydraulics	
Quick Coupler	

Generator

Towable?	
Trailer VIN	
Trailer GVWR (Gross Vehicle Weight Rating)	
Is this trailer titled?	
Trailer Brakes	
kW Output / Power Rating (kW)	

Bucket Truck

Lift Make/Model	
Lift SN Plate	
Date of Last Periodic / Annual Inspection	
Work Basket	
Outriggers / Stabilizers	

Service/Specialty Truck

Auxiliary Engine	No
Auxiliary Fuel Tank	Yes
Lube System	No
Air Compressor	No
Make/ Model	
Welder	No
Make/ Model	
Crane	No

Direct To Auction Form

Make/ Model	
Hitch	No
Hitch Type	
Other Hitch Type	

Tank Trucks

Tank Size (Gallons)	
Water Spray System	

Trailer

Trailer GVWR (Gross Vehicle Weight Rating)	
Is this trailer titled?	
Trailer Brakes	
Hitch	
Other Hitch Type	

Other Features & Attachments

OMM (Operator & Maintenance Manual)	Yes
Other Features & Attachments	Storage boxes on both sides of the truck, roof rack














































360 Walkaround Photos

Exterior Walkaround Photos					
----------------------------	--	--	--	--	--

General Appearance

Close-Up Exterior Photos					
--------------------------	--	--	--	--	--























Direct To Auction Form

					
					
					
					
					
					
					
					
					
Exterior Comments	Chipped paint, surface rust observe, bent running-boards, Right side, mirror housing damaged, front bumper damage, we are bumper damage				






Control Station

Control Station					
					

Direct To Auction Form





					
					
					
					
					
Control Station Overall Comments	Dirty cab, ripped driver seat, and you are in bed and				

Engine

Engine Data Plate				
Engine Compartment				
Engine Type (Make, Model, Cylinders, Hp)	Cummins 6.7 turbo diesel			
Engine Overall Comments	Hood struts worn not holding hood in the up position			

Drivetrain Components







Direct To Auction Form

Drivetrain Photos					
Drivetrain Comments					

Hydraulics

Hydraulic Pump/Fittings/Hoses/Cylinders/Pins	
Hydraulic System Comments	











Chassis

Chassis Photos					
					
					
Comments					


Underbody Inspection Points

Underbody Photos					
					
Underbody Comments					

Attachments

Attachment Photos					
					

Direct To Auction Form

	
Attachment Comments	

Functionality Assessment

Is this machine operable?	Yes
Video - Operational or 360	Click to Download
Comments	Damage front bumper, damage rear bumper, cracked side view mirror housing, surface rest observed, Ripped driver seat