


Seller Onboarded Machine v2.0

General Info

B&B Stock Number	A9799925
Category	Excavator
Year	2012
Make	Caterpillar
Model	308DCR
Serial Number / VIN	CAT0308DLHSA01805
Serial Number Plate / VIN Sticker	 <p>The image shows a close-up of a yellow metal surface on a Caterpillar machine. At the top, the VIN 'CAT0308DLHSA01805' is stamped in metal. Below it is a black identification sticker with the following text: 'MODEL NUMBER 308D', 'CAT CATERPILLAR' logo, 'PRODUCT IDENTIFICATION NUMBER *CAT0308DLHSA01805*', a barcode, 'CATERPILLAR INC. PEORIA, IL 61629 USA', and 'MADE IN JAPAN'. At the bottom of the sticker is a small number '312-7990X'. Below the sticker is a white label with the text '308DCR-2'.</p>
	08-05-2024 09:29 AM
Hour Meter or Odometer Reading	3424.4

Seller Onboarded Machine v2.0

Hour Meter or Odometer Photo	
	08-05-2024 09:30 AM

Dimensions

Overall Length (ft and inches)	19.07
Overall Width (ft and inches)	7.62
Overall Height (ft and inches)	8.5
Operational Weight (lbs)	17306.3

Off Highway Equipment

Travel System	Track Undercarriage
Fuel Type	Diesel
Control Station Type	Enclosed Cab (EROPS)
Operator Controls	Pilot Controls
Seat Type	Fixed
A/C	Yes
Heat	Yes
Radio	Yes
Reverse Camera	No
All of the above are fully functional	Yes

Excavator

Blade	Yes
Bucket	Yes







Seller Onboarded Machine v2.0

Bucket Size (yd3 / inches)	.4
Auxiliary Hydraulics	No
Thumb	No
Extended Stick Option	No
Quick Coupler	No
Grade Control	N/A


Other Features & Attachments

OMM (Operator & Maintenance Manual)	N/A
-------------------------------------	-----


360 Walkaround Photos

<p>Exterior Walkaround Photos</p>			
			


Seller Onboarded Machine v2.0




General Appearance







Seller Onboarded Machine v2.0



Control Station



Seller Onboarded Machine v2.0

			
			
Control Station Overall Comments	Cabin is in great shape. Blows very cold ac. Controls are smooth and no rip seat.		


Engine

Seller Onboarded Machine v2.0








Engine Data Plate



Engine Compartment




















Seller Onboarded Machine v2.0

			
			
			
Engine Type (Make, Model, Cylinders, Hp)	Caterpillar 308DCR, 4 cylinder, 57.7hp		
Engine Overall Comments	All fluids are full. Engine starts instantly. Feels like a new machine.		

Drivetrain Components


Drivetrain and Underbody Photos			
			

Seller Onboarded Machine v2.0


			
			
			
			
			
			
<p>Drivetrain and Underbody Comments</p>	<p>Original paint intact. Still very clean. Undercarriage is in great condition.</p>		

Hydraulics


Seller Onboarded Machine v2.0












Seller Onboarded Machine v2.0



Seller Onboarded Machine v2.0

	
<p>Hydraulic System Comments</p>	<p>Pump is clean and dry. No work has done prior. No leaks anywhere in the machine.</p>










Chassis

<p>Chassis Photos</p>			
			
			

Seller Onboarded Machine v2.0

			
Comments	Frame in great shape, no issue at all.		

Attachments

Attachment Photos			
			
			
Attachment Comments	1 bucket and a blade		

Functionality Assessment

Is this machine fully operable?	Yes
Video - Operational or 360	Click to Download
What's great about this machine	Low hours, cab is in great shape, windshield is like new, ac/heating work extremely well. Overall, in great condition.
What needs work	Nothing.