

Seller Onboarded Machine v2.0

General Info

B&B Stock Number	A1687897
Category	Excavator
Year	2008
Make	Caterpillar
Model	308D
Serial Number / VIN	CAT0308DCJPS00203
Serial Number Plate / VIN Sticker	
	09-02-2024 08:39 PM
Hour Meter or Odometer Reading	2613.6

Seller Onboarded Machine v2.0

Hour Meter or Odometer Photo	
09-02-2024 08:44 PM	

Dimensions

Overall Length (ft and inches)	19.07
Overall Width (ft and inches)	7.62
Overall Height (ft and inches)	8.5
Operational Weight (lbs)	17307

Off Highway Equipment

Travel System	Track Undercarriage
Fuel Type	Diesel
Control Station Type	Enclosed Cab (EROPS)
Operator Controls	Pilot Controls
Seat Type	Fixed
A/C	Yes
Heat	Yes
Radio	Yes
Reverse Camera	No
All of the above are fully functional	N/A

Excavator

Blade	Yes
Bucket	Yes







Seller Onboarded Machine v2.0

Bucket Size (yd3 / inches)	0.4
Auxiliary Hydraulics	No
Thumb	No
Extended Stick Option	No
Quick Coupler	No
Grade Control	N/A

Other Features & Attachments







OMM (Operator & Maintenance Manual)	N/A
Other Features & Attachments	Comes with 1 Cat bucket and 1 Taguchi grapple.

360 Walkaround Photos







<p>Exterior Walkaround Photos</p>			
			

General Appearance






Seller Onboarded Machine v2.0

<p>Close-Up Exterior Photos</p>			
			
<p>Exterior Comments</p>	<p>Exterior overall in great condition. Door open and close. All light works. Clean machine.</p>		

Control Station

<p>Control Station</p>			
			

Seller Onboarded Machine v2.0

			
			
Control Station Overall Comments	All safety features are all operable. Ac/heating/radio working normally. No ripped seat. No crack windshield or windows.		

Engine

Seller Onboarded Machine v2.0







Engine Data Plate












Engine Compartment



Seller Onboarded Machine v2.0

			
			
Engine Type (Make, Model, Cylinders, Hp)	Mitsubishi, 4M40TL, 4 cylinders, 57.7hp		
Engine Overall Comments	Engine turns on instantly. Battery is working great.		










Drivetrain Components

Drivetrain and Underbody Photos			
			
			


Seller Onboarded Machine v2.0

		
<p>Drivetrain and Underbody Comments</p>	<p>Clean and dry. No issue.</p>	

Hydraulics

<p>Hydraulic Pump/Fittings/Hoses/Cylinders/Pin s</p>			
			
			








Seller Onboarded Machine v2.0



Hydraulic System Comments	Punp is clean and very dry. No leaks anywherr.
---------------------------	--

Chassis



Seller Onboarded Machine v2.0

Chassis Photos			
			
			
Comments	Machine frame is very good. No issue.		

Attachments

Attachment Photos			
			

Seller Onboarded Machine v2.0

			
Attachment Comments	Machine comes with 1 digging bucket and 1 Taguchi grapple. Working great with no issue.		

Functionality Assessment

Is this machine fully operable?	Yes
Video - Operational or 360	Click to Download
What's great about this machine	Everything is working as it should. Cabin is in great shape with heating and ac.
What needs work	No work needed.