



## Direct To Auction Form

### General Info

B&B Stock Number	A6465563
Category	Service Truck
Year	2009
Make	Ram
Model	4500
Fleet ID	3119
Serial Number / VIN	3D6WC66L79G522987
Serial Number Plate / VIN Sticker	
Hour Meter Reading	223077
Hour Meter Photo	

### Dimensions

Overall Length (ft and inches)	22' 2"
Overall Width (ft and inches)	7' 10"
Overall Height (ft and inches)	7' 5"
Wheel Base (ft and inches) - ON HIGHWAY MACHINES	13' 11"
Operational Weight (lbs)	

## Direct To Auction Form

### Off Highway Equipment

Travel System	
Comments	
Drive Type	
Comments	
Fuel Type	
Control Station Type	
Operator Controls	
A/C	
Heat	
Radio	
Reverse Camera	

### All On-Highway Trucks

Is this vehicle titled?	Yes
Cab Type	Regular / Day Cab
Drive Type	4X2
Comments	
Transmission	Automatic
Fuel Type	Diesel
PTO	No
Engine Brake	No
Air Brakes	No
A/C	Yes
Heat	Yes
Radio	Yes
Rear Camera	No
Cruise Control	Yes
Over Drive	Yes

### Backhoe

Loader Bucket	
Loader Bucket Size (yd3 / inches)	
Digging Bucket	
Bucket Size (yd3 / inches)	
Extend-a-hoe	

## Direct To Auction Form

Outriggers/Stabilizers	
Auxiliary Hydraulics	
Quick Coupler	

## Bulldozer

Blade	
Blade Type	
Ripper	
GPS/Grade Control System	
System Make/Model	

## Compact Track Loader

High Flow	
Loader Bucket	
Bucket Size (yd <sup>3</sup> / inches)	
Auxiliary Hydraulics	
Quick Coupler	

## Compactor

Blade	
Vibratory System	
Water Spray System	

## Excavator

Blade	
Bucket	
Bucket Size (yd <sup>3</sup> / inches)	
Auxiliary Hydraulics	
Thumb	
Thumb Type	
Extended Stick Option	
Stick Length (ft. in.)	
Quick Coupler	

## Forklift

Forks	
Length x Width (inches)	
Side Shift	

## Direct To Auction Form

### Lifts

Jib	
Outriggers/Stabilizers	
Hydraulic Leveling	
Electrical Power to Platform	

### Motor Grader

Ripper	
Blade	
Push Block	
Front/Mid Scarifier	
GPS/Grade Control System	
System Make/Model	

### Scraper

Engine Configuration	
Elevating Bowl	
GPS/Grade Control System	
System Make/Model	

### Skid Steer

Loader Bucket	
Bucket Size (yd3 / inches)	
High Flow	
Auxiliary Hydraulics	
Quick Coupler	

### Skip Loader

Loader Bucket	
Bucket Size (yd3 / inches)	
Box Blade	
Auxiliary Hydraulics	
Quick Coupler	

### Telehandler

Forks	
Length x Width (inches)	
Work Basket	

## Direct To Auction Form

Outriggers/Stabilizers	
Hydraulic Leveling	
Side Shift	
Quick Coupler	

## Wheel Loader

Loader Bucket	
Bucket Size (yd3 / inches)	
Forks	
Length x Width (inches)	
Auxiliary Hydraulics	
Quick Coupler	

## Generator

Towable?	
Trailer VIN	
Trailer GVWR (Gross Vehicle Weight Rating)	
Is this trailer titled?	
Trailer Brakes	
kW Output / Power Rating (kW)	

## Bucket Truck

Lift Make/Model	
Lift SN Plate	
Date of Last Periodic / Annual Inspection	
Work Basket	
Outriggers / Stabilizers	

## Service/Specialty Truck

Auxiliary Engine	No
Auxiliary Fuel Tank	No
Lube System	No
Air Compressor	No
Make/ Model	
Welder	No
Make/ Model	
Crane	No

### Direct To Auction Form

Make/ Model	
Hitch	No
Hitch Type	
Other Hitch Type	

### Tank Trucks

Tank Size (Gallons)	
Water Spray System	


### Trailer

Trailer GVWR (Gross Vehicle Weight Rating)	
Is this trailer titled?	
Trailer Brakes	
Hitch	
Other Hitch Type	


### Other Features & Attachments

OMM (Operator & Maintenance Manual)	Yes
Other Features & Attachments	Flatbed

### 360 Walkaround Photos

Exterior Walkaround Photos					
----------------------------	--	--	--	--	--
























### General Appearance

Close-Up Exterior Photos					
--------------------------	--	--	--	--	--



## Direct To Auction Form

					
					
<b>Exterior Comments</b>	Surface rust throughout exterior, Cracked windshield, Clearcoat peeling off,				





## Control Station

<b>Control Station</b>					
					
					
					
					
<b>Control Station Overall Comments</b>	Check engine light on, driver seat ripped, dirty cab				

## Engine

<b>Engine Data Plate</b>					
<b>Engine Compartment</b>					
<b>Engine Type (Make, Model, Cylinders, Hp)</b>	Cummins turbo diesel				
<b>Engine Overall Comments</b>	Could not get hood to open, possible fluid leak				

## Drivetrain Components

<b>Drivetrain Photos</b>					
--------------------------	---	---	--	---	--


## Direct To Auction Form

Drivetrain Comments	
---------------------	--

### Hydraulics

Hydraulic Pump/Fittings/Hoses/Cylinders/Pins	
Hydraulic System Comments	

### Chassis

Chassis Photos	
Comments	

### Underbody Inspection Points

Underbody Photos	
Underbody Comments	

### Attachments

Attachment Photos	
Attachment Comments	

### Functionality Assessment

Is this machine operable?	Yes
Video - Operational or 360	
Comments	Check engine light on, hood, unable to be opened, possible fluid leak under engine, Surface rust observed, driver seat, torn