

## Seller Onboarded Machine v2.0

### General Info

B&B Stock Number	A5386549
Category	Excavator
Year	2015
Make	Hitachi
Model	ZX55UR-5B
Serial Number / VIN	HCMAFE0H00050098
Serial Number Plate / VIN Sticker	
	12-05-2024 05:32 PM
Hour Meter or Odometer Reading	1998.1

## Seller Onboarded Machine v2.0

Hour Meter or Odometer Photo



12-05-2024 05:33 PM

## Dimensions

Overall Length (ft and inches)	17.32ft
Overall Width (ft and inches)	6.56ft
Overall Height (ft and inches)	8.5ft
Operational Weight (lbs)	17953lbs

## Off Highway Equipment

Travel System	Track Undercarriage
Fuel Type	Diesel
Control Station Type	Enclosed Cab (EROPS)

## Seller Onboarded Machine v2.0

Operator Controls	Pilot Controls
Seat Type	Fixed
A/C	Yes
Heat	Yes
Radio	Yes
Reverse Camera	No
All of the above are fully functional	Yes










## Excavator

Blade	Yes
Bucket	Yes
Auxiliary Hydraulics	No
Thumb	No
Extended Stick Option	No
Quick Coupler	No
Grade Control	N/A


## Other Features & Attachments

OMM (Operator & Maintenance Manual)	N/A
-------------------------------------	-----








## Full Machine Photos

Full Machine Photos			
			
			

Seller Onboarded Machine v2.0














General Appearance

Close-Up Exterior Photos			
			
			
Exterior Comments	Exterior is good overall. All doors open and close normally. All lighting works.		

Control Station








**Seller Onboarded Machine v2.0**

Control Station			
			
			
			







## Seller Onboarded Machine v2.0

Control Station Overall Comments	Cab is in great shape. All safety features work as it should. Ac/heating/radio work normally.
----------------------------------	---






## Engine

Engine Data Plate	 <p>EMISSION CONTROL INFORMATION THIS ENGINE COMPLIES WITH U.S.EPA AND CALIFORNIA REGULATIONS FOR 2015 M.Y.NONROAD AND STATIONARY/OFF-ROAD DIESEL ENGINES. ULTRA LOW SULFUR FUEL ONLY. ENGINE FAMILY :FYDXL2.19NDA (195kW&lt;37) DISP. : 2.190 L MODEL : 4NNPAC ECU EM EGR DFI PTOX OC REFER TO OWNER'S MANUAL FOR MAINTENANCE AND ADJUSTMENTS. YANMAR CO., LTD. 2015/11</p>		
Engine Manufacturer	Yanmar		
Engine Compartment	  		
	  		












## Seller Onboarded Machine v2.0

			
			
Engine Idle Video - Optional	<a href="#">Click to Download</a>		
Engine Overall Comments	Engine in great shape. Turns on instantly. Very clean and dry engine. No leak anywhere.		

## Drivetrain Components

Drivetrain and Underbody Photos			
			


## Seller Onboarded Machine v2.0

			
			
			
			
			
Drivetrain and Underbody Comments	Clean and dry with no issues.		


## Hydraulics

Hydraulic Pump/Fittings/Hoses/Cylinders/Pins			
--	---	--	---




**Seller Onboarded Machine v2.0**












**Seller Onboarded Machine v2.0**








## Seller Onboarded Machine v2.0

			
Hydraulic System Comments	Pump is clean and dry. No weird noise. Seals are good.		





## Chassis

Chassis Photos			
			
			

## Seller Onboarded Machine v2.0

			
			
Comments	Machine frame and stance are good. Everything is tight and operate normally.		

## Attachments

Attachment Photos			
			

## Seller Onboarded Machine v2.0

Attachment Comments	Comes with blade and bucket. Knuckle boom.
---------------------	--

### Functionality Assessment

Is this machine fully operable?	Yes
Video - Operational or 360	<a href="#">Click to Download</a>
What's great about this machine	This is a great machine. Engine is very clean and strong. Knuckle boom, hydraulic side tilting, able to do very technical dig in tight spot.
What needs work	Nothing.