


## Seller Onboarded Machine v2.0

### General Info

B&B Stock Number	A5046050
Category	Excavator
Year	2006
Make	Caterpillar
Model	308CSR
Serial Number / VIN	CAT0308CACRW02103
Serial Number Plate / VIN Sticker	
	01-17-2025 03:39 PM
Hour Meter or Odometer Reading	3192

## Seller Onboarded Machine v2.0

Hour Meter or Odometer Photo



01-17-2025 03:40 PM

## Dimensions

Overall Length (ft and inches)	19.20
Overall Width (ft and inches)	7.58
Overall Height (ft and inches)	9
Operational Weight (lbs)	17730

## Off Highway Equipment

Travel System	Track Undercarriage
Fuel Type	Diesel
Control Station Type	Enclosed Cab (EROPS)

## Seller Onboarded Machine v2.0

Operator Controls	Pilot Controls
Seat Type	Fixed
A/C	Yes
Heat	Yes
Radio	Yes
Reverse Camera	No
All of the above are fully functional	Yes







## Excavator

Blade	Yes
Bucket	Yes
Bucket Size (yd3 / inches)	0.5
Auxiliary Hydraulics	No
Thumb	No
Extended Stick Option	No
Quick Coupler	No
Grade Control	N/A

## Other Features & Attachments

OMM (Operator & Maintenance Manual)	No
-------------------------------------	----

## Full Machine Photos

Full Machine Photos			
			




## Seller Onboarded Machine v2.0



## General Appearance









### Close-Up Exterior Photos



## Control Station




## Seller Onboarded Machine v2.0

Control Station			
			
			
Control Station Overall Comments	All safety features are operable.		






## Engine

## Seller Onboarded Machine v2.0











<p>Engine Data Plate</p>	
<p>Engine Manufacturer</p>	<p>Mitsubishi</p>
<p>Engine Compartment</p>	



## Seller Onboarded Machine v2.0

			
			
Engine Overall Comments	Engine starts right away. Nothing unusual, no weird noise or smoke.		













## Drivetrain Components

Drivetrain and Underbody Photos			
			
			
			
Drivetrain and Underbody Comments	No crack, no apparent issue.		




## Seller Onboarded Machine v2.0

### Hydraulics





<p>Hydraulic Pump/Fittings/Hoses/Cylinders/Pins</p>			
			
			
			



## Seller Onboarded Machine v2.0

			
Hydraulic System Comments	Pump is good. No leak. No rust on cylinders.		

## Chassis

Chassis Photos	 A yellow excavator is shown from a side profile, parked on a grassy field under a clear blue sky. The excavator's arm is extended to the left.	 A close-up view of the yellow excavator's arm and the black hydraulic cylinder. The arm has a black and white logo on it.	 A close-up view of the yellow excavator's arm and the bucket. The bucket is a reddish-brown color.
	 A view from underneath the excavator's chassis, showing the large circular opening and the internal structure.		
Comments	Mainframe and stance are in good shape. No apparent issue.		

## Attachments

Attachment Photos			
-------------------	---	--	---

## Seller Onboarded Machine v2.0

			
Attachment Comments	Comes with one bucket and blade		

## Functionality Assessment

Is this machine fully operable?	Yes
Video - Operational or 360	<a href="#">Click to Download</a>
What's great about this machine	Machine starts right away. Knuckle boom. No weird noise, no leaks, no cracks. Ac/heating/radio.
What needs work	Nothing