


Inspection Report (Trailer)

General Info

B&B Stock Number	A7507609
Year	2022
Make	EBY
Model	CB14K
Serial Number	4A2CB1626N1023839
Serial Plate Photo	

Dimensions

Data Plate Photo	
Length (ft and inches)	84"
Width (ft and inches)	24"
Max Height (ft and inches)	16"
Dock Height (ft and inches)	2'6"
GVWR (lbs)	14000
GAWR (lbs)	7000

Features and Configuration

PTO Driven	No
Air Ride	No

Inspection Report (Trailer)

Equipment Ramps	Yes
Tilt Deck	No
Dump Trailer	Yes
Deck Extension	No
Tarp System	Yes
Spare Tire	Yes
Winch	No
OMM (Operator & Maintenance Manual)	Yes
Other Configuration Details / Features / Notes	12yd dump

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	    
Operating Video	Click to Download

Trailer Inspection Points

Trailer Inspection Points

General Appearance Photos

Overall Trailer & Underside Photos	    
	    
	    

Inspection Report (Trailer)



Frame & Body

Frame & Deck Condition	5 - Very Light or Minimal Wear
Trailer Lights/Wiring (Stop, Tail, Turn)	5 - Very Light or Minimal Wear
Frame & Body Overall Rating	5 - Very Light or Minimal Wear

Hitch

Hitch Type	Pintle
Strand Wear?	No
Drawbar appears structurally sound	Yes
Overall Hitch Condition	5 - Very Light or Minimal Wear





Brake Components

Brake Type	Electric Brakes
Brake Controller	Yes
Wire Connections	5 - Very Light or Minimal Wear
Brake Shoe Thickness	70%
Emergency Brake/Break-Away Appearance	5 - Very Light or Minimal Wear
Brake Overall Rating	5 - Very Light or Minimal Wear

Suspension

Suspension Overall Rating	5 - Very Light or Minimal Wear
---------------------------	--------------------------------

Wheels & Tires

Tire Brand	Rainier ST			
Tire Size	ST235/80R16			
Loose Lugs	No			
Left Tires - Ratio Remaining	70%			
Left Tire Photos				
Right Tires - Ratio Remaining	70%			

Inspection Report (Trailer)

Right Tire Photos	   
Wheels & Hub Condition	5 - Very Light or Minimal Wear

Hydraulics

Hydraulics Overall Rating	5 - Very Light or Minimal Wear
---------------------------	--------------------------------

Functional Test

Brakes (visual)	5 - Very Light or Minimal Wear
Light System	5 - Very Light or Minimal Wear
Hydraulic Controls	5 - Very Light or Minimal Wear
Winch	5 - Very Light or Minimal Wear

Inspection Summary

Overall Assessment

Inspection Rating Criteria	Rating	Explanation
	5	Light or minimal wear for its age
	4	Expected wear and tear for its age, operates as expected
	3	Above average wear and tear for its age, still operates as expected
	2	Heavy wear, is operable but needs attention
	1	Requires repair(s) to function as expected
Exterior Rating	5 - Very Light or Minimal Wear	
Interior Rating	5 - Very Light or Minimal Wear	
Safety Rating	5 - Very Light or Minimal Wear	
Quality Rating	5 - Very Light or Minimal Wear	
Functionality Rating	5 - Very Light or Minimal Wear	
Overall Rating	5 - Very Light or Minimal Wear	
What's Great About the Machine	The great thing about this trailer is that there were no abnormal noises heard during the functional test	
What Needs Work	NA	
Date/Time	02-26-2025	
Inspector Name	Javier Bocanegra	
Assessment Details	<p>Boom & Bucket provides an on-site visual inspection of the Unit. The inspection of mechanical components may be limited to starting and running the engine and basic hydraulic movements. Any operational tests are limited to low speeds and are not tested under load. The functionality of locking differentials, transmission shifting, all drive axels, brakes, and auxiliary or high flow hydraulics (unless required for an included attachment) cannot be fully verified. Additional information may be available on request. Please see the terms of services on our website for full details.</p>	