

Inspections: Damaged Pole Report

Service Request: 25-00364219 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 5126 Chaugrove Ave

Grid : 1640 420 LLC: 7044

Descriptive Location and Comments:

Street: Chaugrove Ave

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: W. Belvedere Ave

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No ☒

Base Condition:

Bolts ☒

Wires ☒

Conduit ☒

Good

☒

☒

☒

Bad:

☐

☐

☐

Base Type:

Metal ☒

Concrete ☒

Date: 4/15/2025 Inspector's Signature: G. Crowder 8512

Service Request Summary Report
25-00304219
Printed Date: Apr 16, 2025 - 4:03:51 PM

Type: BGE-StLight Pole Installation
Created By: Keeva Flood
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00304219
Priority: Standard
Status: Pending
Status Date: Apr 16, 2025 4:02:35 PM
Created Date: Apr 13, 2025 3:56:32 PM
Overdue on: Jun 17, 2025 2:54:05 PM
Closed on:

Location: 5127 CHALGROVE AVE, Baltimore City,
21215

Location Details:

Description: The street light is down across the street in front of the property.

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Refused

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
---------------	--------	-------------	---------	----------------	-------------

Assign inspector	Complete	Gregory Crowder	Assigned		4/16/2025 3:57 PM
------------------	----------	-----------------	----------	--	-------------------

Service Response	Not Started				
------------------	-------------	--	--	--	--

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
------------------	---------------------	-------------------

Assign inspector	GRID #	1040420
Assign inspector	LLC / POLE #	7044
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
---------	------------	--------------	------------