

Inspections: Damaged Pole Report

Service Request: 25-00368813 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 950 W. Franklin St
 Grid : 3010 110 LLC: 7063

Descriptive Location and Comments:

Street: W. Franklin St
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: N. Schroeder St

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' ☒
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 ☒
 250 _____
 400 _____
 1000 _____

Arm:

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts
 Wires
 Conduit

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete ☒

Date: 5/6/2025 Inspector's Signature: G. Crowder - 8512



950 W. Franklin St

25 ft CH LED

Service Request Summary Report
25-00368813
Printed Date: May 6, 2025 - 3:28:57 PM

Type: BGE-StLight Pole Installation
Created By: Theresa Wharton-Johnson
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 25-00368813
Priority: Urgent
Status: Pending
Status Date: May 06, 2025 3:28:53 PM
Created Date: May 03, 2025 8:01:19 PM
Overdue on: Jul 07, 2025 3:23:44 PM
Closed on:

Location: 950 W FRANKLIN ST, Baltimore City,
21223

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
concerned citizen			

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		5/6/2025 3:27 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010110
Assign inspector	LLC / POLE #	7063
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	Other
Assign inspector	Base type	Metal