

Inspections: Damaged Pole Report

Service Request: 25-00458048 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 701 West Melrose Ave

Grid: 1050110 LLC: 7035

Descriptive Location and Comments:

Street: W. Melrose Ave

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction: N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Kenmore Rd

Condition of Pole:

Pole Size:

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ☒

Missing ☒

12' ☒

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor ☒

100 _____

6' _____

Damaged _____

PMA ☒

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED _____

250 _____

20' _____

Bolton Hill _____

Other _____

400 _____

Other _____

Victorian Acorn _____

1000 _____

Other _____

Other _____

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes ☒
No _____

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete _____

Date: 6/3/2024 Inspector's Signature: A. Crowder-8512



5700 Kenmore Rd
701 West Melrose Ave

Service Request Summary Report
25-00458048
Printed Date: Jun 3, 2025 - 3:25:16 PM

Type: BGE-StLight Pole Installation
Created By: Tahsen Carr
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00458048
Priority: Standard
Status: Pending
Status Date: Jun 03, 2025 3:20:49 PM
Created Date: Jun 01, 2025 4:03:35 PM
Overdue on: Aug 04, 2025 4:55:59 PM
Closed on:

Location: 701 W MELROSE AVE, Baltimore City,
21210
Location Details:
Description: Pole number is
15035

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Patricia Peltz		thepeltz/smily@aol.com	+1 (443) 722-0878

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		6/3/2025 3:20 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1050110
Assign inspector	LLC / POLE #	7035
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
---------	------------	--------------	------------