

Inspections: Damaged Pole Report

Service Request: 25-00487369 Sector: 2 Gateway: _____ Primary: _____
 Location on Service Request: 3825 Greenspring Ave
 Grid : 1030 320 LLC: 7258

Descriptive Location and Comments:

Street: Greenspring Ave
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: Keyworth Ave

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' ☒
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Neet new base

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 ☒
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒


Base Condition: Good _____ Bad: _____

Bolts ☒
 Wires ☒
 Conduit ☒

Base Type:

Metal ☒
 Concrete _____

Date: 6 / 10 / 2025 Inspector's Signature: G. Crowder - 8512



Service Request Summary Report
25-00487369
Printed Date: Jun 10, 2025 - 3:21:44 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00487369
Priority: Standard
Status: Pending
Status Date: Jun 10, 2025 3:19:44 PM
Created Date: Jun 10, 2025 3:16:52 PM
Overdue on: Aug 12, 2025 3:16:52 PM
Closed on:

Location: 3825 GREENSPRING AVE, Baltimore City,
21211
Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		6/10/2025 3:19 PM

Service Response Not Started

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1030320
Assign inspector	LLC / POLE #	7258
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
---------	------------	--------------	------------