

Inspections: Damaged Pole Report

Service Request: 25-00533361 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 2107 Barclay St
 Grid : 2020130 LLC: 7257

Descriptive Location and Comments:

Street: Barclay St
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O ☒ E/O _____ S/O _____ W/O _____
 Street or Landmark: E. 21st

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' _____
 30' ☒
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 ☒
 250 _____
 400 _____
 1000 _____

Arm:

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal _____
 Concrete ☒

Date: 6/26/2025 Inspector's Signature: G. Crowder 8512



2107 Barclay St

Service Request Summary Report
25-00533361
Printed Date: Jun 26, 2025 - 3:19:09 PM

Type: BGE-StLight Pole Installation
Created By: Lynne Hellman
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00533361
Priority: Standard
Status: Pending
Status Date: Jun 26, 2025 3:18:56 PM
Created Date: Jun 24, 2025 7:19:52 PM
Overdue on: Aug 27, 2025 3:53:39 PM
Closed on:

Location: 2107 BARCLAY ST, Baltimore City,
21218

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

annon annon

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		6/26/2025 3:17 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	2020130
Assign inspector	LLC / POLE #	7257
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	Other
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
---------	------------	--------------	------------